From:	Date:	Veh No: 54754132 Yr Regn: 15/06/15			
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /			
OD / TP) WS / TP RES / C		Truck / Trailer or			
To Inspect Vehicle No:	SKT5413t	Make: Togoto conollo Altis c.c 1598			
at Workshop m/s	ninten	Colour Schu A/C: Insured / Std / NI / NA			
of		Sp.Reading £7.13.4 T/Radio: Insured / Std / NI / NA			
Insured:	SFN 18190	Eng/No:			
Policy No.		C/No: MRD53REH10.4537409			
Claims No.		Gen. Cond Good / Fair / Poor / Burnt			
Sum Insured:	Excess:	Steering: Larred / Leaked / Burnt or			
(Client's Record)		Brake: Inorder / Jammed / Leaked / Burnt or			
Make of Veh:		Modi: Nil S/R/m / STD A/Rim or			
		Tyre Size: F: 205/57-7/6			
(Policy Condition)		R:			
Remark: The veh had cor	mmenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /			
repair at the tim	ne of inspection.	TOYO / YOKO or			
Bal. or Market Value:	\$44k.	Front 7 Rear 7			
IDAC Accident Rport:	Consistent?: Yes or No	R/Bal. mm R/Bal. mm			
GIA / PR Seen:	Consistent?: Yes or No	L/Bal. L/Bal. mm			
Est. Repairs: 3	days Res.: Yes or No	D.O.A. 09/09/27 D.O.I. 13/09/27			
Lum Sum: 20	% 3 Val.: Yes or No	Survey held at			
CA / REV / REP. /	24 HRS (\ 0)	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or			
Date: Pe	rson Contacted: Vehicle: IN / OUT				
	17H V 140C	The U/C / Chassis frame / Body Structure affected due to collision.			
2/5/174/50	Instruction der Minhous	Leveny			
0///00/3	1 100 inpoling	Herchay			
		J.			
_					
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:			
1)	: Final Report	Resurvey No. of Trip: Survey Fee:			
Date/Time, File Return to?		Transportation:			
2)	Add Fe				
		: Interview (\$) Photos			
Report Format :		: Tech. Invs (\$) Others			
Lump Sum / I.B.I: (\$)	: Weekend (\$			
		TOTAL			

NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43 #07-97 Singapore 520436 Tel: (65) 9674 1991 ☑ nineteenautowerks@gmail.com Not Auffreid

2/5 € 11 00

13/8/22

NINETEEN

ESTIMATE

DATE:

DOA:

VEHICLE NO:

MAKE & MODEL:

12-Sep-22

9-Sep-22

SKT 5413 Z

Toyota Corolla Altis

				Toyota corona Aitis		
DESCRIPTION	QUANTITY	AMOUNT		TOTAL		
LIST ITEMS						
Rear bumper	1	\$856.00	184.10	ss/De	\$856.00 _	
Rear bumper side retainer	2	\$86.00		11	\$172.00 X	
Rear bumper reflector	2	\$105.40		11	\$210.80	
Rear bumper reinforcement	1	\$358.00		R	\$358.00	
Rear reinforcement sponge	1	\$176.50		NZ	\$176.50	
Rear bumper reinforcement bracket	2	\$125.70		11	\$251.40 🔀	
Rear end panel	1	\$788.50		R	\$788.50 🏏	
Rear end panel top garnish	1	\$261.00		11	\$261.00	
		Total			\$3,074.20	
		Less 25%			\$768.55	
					\$2,305.65	
SPECIAL NETT ITEMS						
Sundries	1	\$60.00		11	\$60.00 🗶	
Rear bumper clips (set)	1	\$100.00		1ec	\$100.00	
Reverse sensor with module	1	\$300.00		Su	\$300.00 💉	
Reverse camera	1	\$350.00		11	\$350.00	
Rear end panel sealant	1	\$100.00		17	\$100.00	
Rear end panel top garnish clips (set)	1	\$50.00		17	\$50.00	
					\$960.00	
	Pa	rts Total			\$3,265.65	
LABOUR CHARGES						
Panel beating					\$1,000.00 3	
Spray painting					\$1,200.00 \$	

Labour Total

Total Parts and Labour Cost of Repair

Check wiring system after disconnect & connect

Remove & refit reverse sensor & test

Remove & refit reverse camera & test

To apply undercoating for rust roofing

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date

184.1 252 438.07 157807

\$100.00 X

17 \$100.00 Q

<u>∧∽</u> \$100.00 🖔

\$2,600.00

\$5,865.65