



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6174B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR GLASS LH (DISC 30%) (CONSISTENT)	CRACKED	161.70	113.19
1	MIRROR ASSY ,LH (CONSISTENT)	NOT NECESSARY	1,399.60	-
1	MIRROR LAMP LH (CONSISTENT)	NOT NECESSARY	73.80	-
1	COVER ,OUTER MIRROR ,LH (CONSISTENT)	TO REPAIR SEE LABOUR	142.30	-
			1,777.40	113.19
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF COVER ,OUTER MIRROR ,LH .		338.00	50.00
	SPRAY PAINT.		180.00	50.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .		120.00	40.00
	TO APPLY RUST -PROOFING ON AFFECTED AREA .	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			898.00	140.00
GRAND TOTAL			2,675.40	253.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				200.00

Report Ref No. CC4/ASM22008979/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.