

9/13/22, 5:07 PM


<https://vacswb.smrt.com.sg/Estimation.aspx>

Case Details

Case Reference Number : TAX/09/22/2025
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6174B

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19333-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 10/09/2022 04:30 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			MIRROR ASSY,LH	1	1,399.60	1,399.60	10.00	1,269.64	Replace	0	0	Not Give	X11
One Time Key In	Main			MIRROR GLASS LH	1	161.70	161.70	30.00	113.19	Replace	1	113.19	Replace	cm
One Time Key In	Main			MIRROR LAMP LH	1	73.80	73.80	10.00	66.42	Replace	0	0	Not Give	X11
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	142.30	142.30	30.00	99.61	Replace	1	0	Repair	R
Total Spare Part Cost									1,638.86	Surveyor Total		113.19		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									1,231.09	Final Sur Total		90.66		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	338.00	50.00	
Total:			338.00	50.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY VIEW MIRROR	180.00	50.00	
Total:			180.00	50.00	

Other Cost Detail


<https://vacswb.smrt.com.sg/Estimation.aspx>

9/13/22, 5:07 PM

<https://vacswb.smrt.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>Xm</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40.00	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>Xm</i>	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xm</i>	
Total:			380.00	40.00 /	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,231.09	90.55
Total Labour Cost	338.00	50.00
Total Spray Painting	180.00	50.00
Other	380.00	40.00
Overall Total	2,129.09	230.55
Lump Sum Repair Option	☐	☒
Lump Sum Total	2,150.00	250.00
Surveyor Approved Amount		250.00
No of Repair Days*	3	1
Remarks	-	Lump sum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9991 0088 email: rasul@lkkauto.com
Surveyor Name		Rasul
Signature		
Survey Date	13/09/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

<https://vacswb.smrt.com.sg/Estimation.aspx>