

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22008982/RYA3Q2**Date:** 17/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210137598
<b>Claimant Vehicle No :</b>	SHF33D	<b>Insured Vehicle No :</b>	SLJ4023M
Date of Loss:	12/09/2022	Nature of Claim:	TP
		Claim No:	5481994280SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF33D</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G94525
Reg. Date:	01/12/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU503091991
Colour:	Maroon	Odometer:	113339 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,370.00	756.69	6,613.31	89.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,292.00	760.00	1,532.00	66.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>9,662.00</b>	<b>1,516.69</b>	<b>8,145.31</b>	<b>84.30</b>
<b>+ Loss of Use (3.8 x S\$50.00/day) (S\$)</b>		187.50		
<b>+ Car Rental (3.8 x S\$79.18/day) (S\$)</b>		296.93		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,003.12</b>		

INSPECTION

Date of Assignment:	13/09/2022	
Date Inspected:	13/09/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RETAINER ,FR WHEEL LH (DISC 25%)	Necessary	3.50 F	*2.63 F
2	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	59.10 F	*44.33 F
3	1		*MOULDING ,FRONT BUMPER SIDE ,LH (DISC 25%)	Scratched	103.70 F	*77.78 F
4	10		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	48.00 F	*36.00 F
5	1		*COVER ,FR BUMPER (DISC 25%)	Scratched	565.60 F	*424.20 F
6	1		*CAP SUB-ASSY ,WHEEL (DISC 25%)	Scratched	229.00 F	*171.75 F
7	1		*PAD ,FR WHEEL LH	Not Necessary	65.00 F	*- F
8	1		*LINER ,FR FENDER ,LH	Not Necessary	227.80 F	*- F
9	1		*UNIT ,HEADLAMP ,LH	Not Necessary	2,852.40 F	*- F
10	1		*COVER ,FR BUMPER LH	Not Necessary	32.70 F	*- F
11	1		*SUPPORT ,FR BUMPER LH	Not Necessary	86.20 F	*- F
12	1		*WHEEL ,DSIC FRONT	Not Necessary	2,036.30 F	*- F
13	1		*FENDER SUB-ASSY ,FR ,LH	Repair	1,060.70 F	*- F
Total Parts (\$\$)						7,370.00 756.69

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	300.00
2	SPRAY PAINT	New	1,116.00	400.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,292.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >