

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008989/TVY3M4**Date:** 11/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCNA00107552201		
Claimant Vehicle No :	PC6680S	Insured Vehicle No :	SMQ6567Z		
Date of Loss:	07/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206516/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6680S		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD2750129
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	KDH2230034078
Colour:	Purple	Odometer:	394972 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/R15	Rear Tyre Size:	195/R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,143.50	2,911.75	12,231.75	80.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,570.00	2,710.00	63.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,423.50	4,481.75	14,941.75	76.93
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	19,423.50	3,600.00	15,823.50	81.47
+ GST 8.00/8.00% (\$\$)	1,553.88	288.00	1,265.88	81.47
Nett Amount (\$\$)	20,977.38	3,888.00	17,089.38	81.47

INSPECTION

Date of Assignment:	13/09/2022		
Date Inspected:	14/09/2022	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6680S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,001.00 FL	*1,855.00 FL
2	1		*TAILGATE CENTRE EMBLEM	Cracked	48.00 FL	*48.00 FL
3	1		*TAILGATE OUTER HANDLE	Not Necessary	430.00 FL	*- FL
4	1		*TAILGATE RH NUMBER PLATE LAMP	Not Necessary	112.00 FL	*- FL
5	1		*TAILGATE LH NUMBER PLATE LAMP	Not Necessary	112.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	387.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	505.00 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	398.00 FL	*- FL
9	1		*TAILGATE LOCK CATCH	Not Necessary	87.00 FL	*- FL
10	1		*TAILGATE CENTRAL LOCKING ASSY	Not Necessary	445.00 FL	*- FL
11	1		*TAILGATE RH DAMPER	Not Necessary	371.00 FL	*- FL
12	1		*TAILGATE LH DAMPER	Not Necessary	371.00 FL	*- FL
13	1		*TAILGATE RH HINGE	Not Necessary	178.00 FL	*- FL
14	1		*TAILGATE LH HINGE	Not Necessary	178.00 FL	*- FL
15	1		*REAR BUMPER RH SIDE RETAINER	Deformed	71.00 FL	*71.00 FL
16	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	71.00 FL	*- FL
17	1		*REAR BUMPER LOWER BRACKETS (4PCS)	Bent (1Piece Only)	96.00 FL	*24.00 FL
18	1		*RH TAILLAMP ASSY	Not Necessary	389.00 FL	*- FL
19	1		*RH TAILLAMP LOWER COVER	Not Necessary	134.00 FL	*- FL
20	1		*RH TAILLAMP LOWER COVER RETAINER	Not Necessary	171.00 FL	*- FL
21	1		*RH TAILLAMP PANEL	Not Necessary	571.00 FL	*- FL
22	1		*LH TAILLAMP ASSY	Not Necessary	389.00 FL	*- FL
23	1		*LH TAILLAMP LOWER COVER	Not Necessary	134.00 FL	*- FL
24	1		*LH TAILLAMP LOWER COVER RETAINER	Not Necessary	171.00 FL	*- FL
25	1		*LH TAILLAMP PANEL	Not Necessary	571.00 FL	*- FL
26	1		*END PANEL (OUTER)	Bent	567.00 FL	*567.00 FL
27	1		*END PANEL (INNER)	Not Necessary	789.00 FL	*- FL
28	1		*END PANEL INNER TOP GARNISH	Not Necessary	374.00 FL	*- FL
29	1		*END RH SIDE PANEL	Not Necessary	251.00 FL	*- FL
30	1		*END LH SIDE PANEL	Not Necessary	251.00 FL	*- FL
31	1		*REAR RH FENDER INNER TRIM	Not Necessary	781.00 FL	*- FL
32	1		*REAR LH FENDER INNER TRIM	Not Necessary	781.00 FL	*- FL
33	1		*SPARE TYRE CARRIAGE	Not Necessary	404.00 FL	*- FL
34	1		*SPARE TYRE CARRIAGE BRACKET	Not Necessary	178.00 FL	*- FL
35	1		*SPARE TYRE CARRIAGE BRACKET SCREW	Not Necessary	121.00 FL	*- FL
36	1		*EXHAUST SILENCER	Not Necessary	349.00 FL	*- FL
37	1		*EXHAUST SILENCER GASKET	Not Necessary	37.00 FL	*- FL
38	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
39	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*40.00 FS
40	1		*TAILGATE HIGH SPOILER	Not Necessary	1,250.00 FS	*- FS
41	1		*TAILGATE CENTRE SPOILER	Not Necessary	950.00 FS	*- FS
42	1		*TAILGATE OUTER HANDLE SPOILER	Not Necessary	500.00 FS	*- FS
43	1		*TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*28.00 FS
44	1		*TAILGATE SEALANT	Not Necessary	120.00 FS	*- FS
45	1		*TAILGATE REVERSE CAMERA	Not Necessary	750.00 FS	*- FS

Report was unsubmitted during this print-out.

1/11/23, 10:00 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
47	1		*REAR BUMPER (AFTER MARKET)	Cracked	1,050.00 FS	*800.00 FS
48	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
49	1		*END PANEL JOINT SEALANT (OUTER)	Necessary	80.00 FS	*40.00 FS
50	1		*END PANEL JOINT SEALANT (INNER)	Not Necessary	80.00 FS	*- FS
51	1		*END RH SIDE PANEL JOINT SEALANT	Not Necessary	40.00 FS	*- FS
52	1		*END LH SIDE PANEL JOINT SEALANT	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					18,462.00	3,553.00
- List Item Discount on L Items 25.00/25.00% (S\$)					3,318.50	641.25
Total Parts (S\$)					15,143.50	2,911.75
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	280.00	120.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	120.00	30.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	180.00	60.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	0.00
9	REMOVE AND REPLACE REAR INNER TRIMS AND GARNISH TO ASSIST REPAIR	New	320.00	0.00
10	REMOVE AND REPLACE REAR BUMPER REVERSE CAMERA TO ASSIST REPAIR	New	100.00	30.00
Gross Labour Cost (S\$)			4,280.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >