

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22008993/UPA3Q2**Date:** 26/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210155263
<b>Claimant Vehicle No :</b>	GX646C	<b>Insured Vehicle No :</b>	SNF6366H
Date of Loss:	12/09/2022	Nature of Claim:	TP
		Claim No:	1961401702SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GX646C</b>	Engine No:	3C3982130
Make & Model:	TOYOTA LITEACE, 2.2 D (M)	Chassis No:	CR425007034
Reg. Date:	16/01/2004 (Man. Year: 2003)	Odometer:	354969 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Maxmiler 6 mm	Rear Left Side:	Maxmiler 6 mm
Front Right Side:	Maxmiler 6 mm	Rear Right Side:	Maxmiler 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,056.45	3,641.34	3,415.11	48.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	1,990.00	1,900.00	48.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,946.45</b>	<b>5,631.34</b>	<b>5,315.11</b>	<b>48.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,946.45</b>	<b>4,500.00</b>	<b>6,446.45</b>	<b>58.89</b>
<b>+ Car Rental (6.5 x S\$100.00/day) (S\$)</b>		650.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,152.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,150.00</b>		

**INSPECTION**

Date of Assignment:	14/09/2022	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	14/09/2022 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	6.0 days	Singapore 470130

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	130.50 FL	*130.50 FL
2	1		*REAR TAILGATE	Badly Dented	1,793.50 FL	*1,615.20 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	508.40 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD	Torn	286.95 FL	*286.95 FL
5	1		*REAR TAILGATE LOCK	Dented /Jammed	223.30 FL	*223.30 FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	65.90 FL	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	219.20 FL	*- FL
8	1		*REAR TAILGATE RUBBER	Twisted	328.48 FL	*299.80 FL
9	1		*REAR TAILLAMPS	N/S Cracked / O/SNot Necessary	771.00 FL	*385.50 FL
10	1		*REAR TAILLAMP PANEL -LH	Dented	461.90 FL	*408.50 FL
11	1		*REAR BUMPER	Distorted	695.20 FL	*488.61 FL
12	2		*REAR BUMPER BRACKETS	Necessary	57.20 FL	*57.20 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	130.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINERS	Necessary	132.40 FL	*132.40 FL
15	1		*REAR END PANEL	Dented	887.90 FL	*680.50 FL
16	1		*REAR END PANEL TOP MOULDING	Serviceable	108.60 FL	*- FL
17	2		*REAR NUMBER PLATE LAMPS	Not Necessary	136.00 FL	*- FL
18	1		*REAR SIDE BODY PANEL -LH	Repair	1,765.50 FL	*- FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
21	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
22	1		*REAR TAILGATE 5 PAX STICKER	Necessary	25.00 FS	*10.00 FS
23	1		*SET REAR REVERSE SENSOR	Not fitted	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,231.93	4,818.46
- List Item Discount on L Items 25.00/25.00% (S\$)	2,175.48	1,177.12
Total Parts (S\$)	7,056.45	3,641.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	0.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	0.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	180.00	80.00
7	PANEL BEATING	New	1,600.00	900.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,890.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >