

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008994/GWY3Q2**Date:** 05/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00205602101

**Claimant Vehicle No :** SMC7473C **Insured Vehicle No :** SMF1140L

Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: SNM22D206159/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMC7473C**

Make & Model: MERCEDES-BENZ GLC 200, 2.0 (A) Engine No: 27492031507394

Reg. Date: 20/07/2018 (Man. Year: 2018) Chassis No: WDC2539422F459760

Colour: Silver Odometer: 61703 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,177.50	2,937.60	4,239.90	59.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	530.00	1,010.00	65.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,717.50</b>	<b>3,467.60</b>	<b>5,249.90</b>	<b>60.22</b>
<b>+ GST 8.00/8.00% (S\$)</b>	697.40	277.41	419.99	60.22
<b>Nett Amount (S\$)</b>	<b>9,414.90</b>	<b>3,745.01</b>	<b>5,669.89</b>	<b>60.22</b>

**INSPECTION**

Date of Assignment: 14/09/2022

Date Inspected: 13/09/2022 Inspected At: Vin's Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive, #03-03, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLC 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC7473C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP	Not Necessary	3,420.00 FL	*- FL
2	1		*FRONT BUMPER	Broken	1,359.00 FL	*1,359.00 FL
3	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	84.00 FL	*- FL
4	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	345.00 FL	*- FL
5	1		*FRONT CENTRE LOWER GRILLE CHROME	Cracked	675.00 FL	*675.00 FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	72.00 FL	*- FL
7	1		*FRONT BUMPER LH LOWER PAD	Not Necessary	214.00 FL	*- FL
8	1		*FRONT BUMPER LH PARKING SENSOR	Cut	288.00 FL	*288.00 FL
9	2		*FRONT BUMPER PARKING SENSOR	Not Necessary	576.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Cracked	171.00 FL	*171.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	435.00 FL	*435.00 FL
12	10		*FRONT BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
13	1		*FRONT LH WHEEL ARCH GARNISH	Broken	246.00 FL	*246.00 FL
					Sub Total (\$\$)	
					7,975.00	3,264.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	
					797.50	326.40
					Total Parts (\$\$)	
					7,177.50	2,937.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET HEADLAMP SYSTEM	New	280.00	0.00
2	TO REPAIR DAMAGES	New	580.00	250.00
3	TO SPRAY PAINTING	New	680.00	280.00
<b>Gross Labour Cost (S\$)</b>			<b>1,540.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >