

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 7037J**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR N/S (N)	DENTED / BENT	1,090.30	1,090.30
1	FRONT DOOR W/STRIP N/S (N)	NECESSARY	134.40	134.40
1	REAR DOOR N/S (N)	BADLY DENTED	1,090.30	1,090.30
1	REAR DOOR W/STRIP N/S (N)	NECESSARY	134.40	134.40
1	REAR DOOR INNER LOCK N/S (N)	NOT NECESSARY	198.30	-
1	REAR DOOR OUTER HANDLE N/S (N)	NOT NECESSARY	94.70	-
1	REAR DOOR TOP OUTER MOULDING N/S (N)	NECESSARY	166.20	166.20
1	REAR DOOR REGULATOR GEAR N/S (N)	BENT	103.40	103.40
1	REAR FENDER GARNISH N/S (N)	GRAZED	160.50	160.50
1	FRONT DOOR PROTECTOR N/S (N)	GRAZED	213.00	213.00
1	REAR DOOR PROTECTOR N/S (N)	GRAZED	130.40	130.40
1	ROCKER GARNISH N/S (N)	GRAZED	737.00	737.00
	LESS 10% DISCOUNT		-425.29	-395.99
			3,827.61	3,563.91
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WHEEL RIM N/S (SN)	TO REPAIR SEE LABOUR	485.00	-
			485.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE REPLACE FRONT & REAR DOOR .INCLUSIVE OF THE REPAIR OF REAR WHEEL RIM N/S. TO SPRAY PAINTING.		780.00	500.00
			780.00	700.00
			1,560.00	1,200.00
<b>GRAND TOTAL</b>			<b>5,872.61</b>	<b>4,763.91</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,800.00</b>

Report Ref No. CS/SMO22009000/Uny3q2

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.