

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Re	ef:	CS/ASM22009002/Aqy3m4
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Da	ite:	27/10/2022
	ATTN: LOH CYNTI	HIA	Co	de:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLW 253Z	Veh. Inspected		SNA 1657C
	Policy No.	GA315912	Coverage (\$)		0.00
	Claim No.	S2M04AVK	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		13/09/2022
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE	c.c		1598
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	KMHLN41ETNU156396	Colour		GREY
	Odometer	92937 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/55 R16	HANKOOK		6 mm
	L/H Front Tyre	215/55 R16	HANKOOK		6 mm
	R/H Rear Tyre	215/55 R16	HANKOOK		6 mm
	L/H Rear Tyre	215/55 R16	HANKOOK		6 mm
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/09/2022	Inspection Date		14/09/2022
	Survey held at	8 KAKI BUKIT AVENUE 4. PREMIER@KAKI BUKIT #03-19 2020 SPRAY PAINTING PTE LTD			
	Repairer				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	•				