

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22009003/RVY3Q2**Date:** 28/04/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SNG4108U **Insured Vehicle No :** SKJ3954U

Date of Loss: 03/09/2022 Nature of Claim: TP Claim No: DMPC2200396H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG4108U**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 2ZRY856279

Reg. Date: 29/07/2022 (Man. Year: 2022) Chassis No: MR2BZ3BE000009847

Colour: Black Odometer: 9176 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	62,392.17	27,056.90	35,335.27	56.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,110.00	5,990.00	6,120.00	50.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,502.17	33,046.90	41,455.27	55.64
Approved Total (Overridden) (S\$)		26,400.00		
(S\$)	74,502.17	26,400.00	48,102.17	64.56
+ GST 8.00/8.00% (S\$)	5,960.17	2,112.00	3,848.17	64.56
Nett Amount (S\$)	80,462.34	28,512.00	51,950.34	64.56

INSPECTION

Date of Assignment: 13/09/2022

Date Inspected: 13/09/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Apr 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG4108U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	798.00 FL	*581.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Cracked	212.00 FL	*212.00 FL
3	1		*FRONT BUMPER SPONGE	Cracked	184.00 FL	*184.00 FL
4	1		*FRONT BUMPER UNDER COVER	Cracked	289.00 FL	*289.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	451.00 FL	*391.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	196.00 FL	*196.00 FL
7	1		*FRONT GRILLE TOP RUBBER	Necessary	75.00 FL	*75.00 FL
8	1		*FRONT GRILLE TOP GARNISH	Not Necessary	159.00 FL	*- FL
9	1		*FRONT GRILLE	Cracked	590.00 FL	*446.00 FL
10	1		*FRONT GRILLE LOGO	Cracked	187.00 FL	*80.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	217.00 FL	*- FL
12	1		*FRONT BUMPER LOWER COVER GARNISH RH	Not Necessary	212.00 FL	*- FL
13	1		*FRONT BUMPER LOWER COVER GARNISH	Not Necessary	389.00 FL	*- FL
14	2		*FRONT BUMPER FOG LAMP	Not Necessary	714.00 FL	*- FL
15	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	260.00 FL	*- FL
16	1		*FRONT WINDSCREEN GLASS	Cracked	1,459.00 FL	*1,319.00 FL
17	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	198.00 FL	*52.00 FL
18	1		*FRONT WIPER GARNISH	Not Necessary	321.00 FL	*- FL
19	1		*FRONT WIPER SIDE GARNISH RUBBER	Not Necessary	65.00 FL	*- FL
20	2		*FRONT CHASSIS FRAME EXTENSION	Repair	1,571.80 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Bent	2,124.00 FL	*1,486.70 FL
22	1		*BONNET	Buckled	1,354.00 FL	*1,267.40 FL
23	1		*BONNET LOWER LOCK	Bent	250.00 FL	*180.20 FL
24	1		*BONNET WEATHERSTRIP	Not Necessary	68.00 FL	*- FL
25	1		*BONNET INSULATOR	Deformed	212.00 FL	*212.00 FL
26	1		*BONNET HINGES	Bent	62.00 FL	*62.00 FL
27	1		*FRONT FENDER	N/S Repair / O/S Bent	1,316.00 FL	*658.00 FL
28	2		*FRONT FENDER INNER PANEL	Not Necessary	1,177.60 FL	*- FL
29	2		*FRONT FENDER INNER SHIELD	Not Necessary	396.00 FL	*- FL
30	2		*FRONT FENDER EMBLEM HYBRID	Necessary	104.00 FL	*62.00 FL
31	2		*FRONT WHEEL HOUSING	Not Necessary	1,396.00 FL	*- FL
32	2		*FRONT FENDER GARNISH	Not Necessary	110.00 FL	*- FL
33	1		*AIRCON CONSENSOR	Bent	1,568.00 FL	*1,133.20 FL
34	1		*AIR CON SUCTION PIPE	Not Necessary	580.00 FL	*- FL
35	1		*AIR CON PRESSURE PIPE	Bent	730.00 FL	*289.00 FL
36	2		*AIR CON CONDENSOR LOWER RUBBER	Not Necessary	65.00 FL	*- FL
37	1		*RADIATOR	Bent	1,780.00 FL	*1,780.00 FL
38	1		*RADIATOR TOP GARNISH	Cracked	280.00 FL	*100.10 FL
39	2		*RADIATOR TOP BRACKET	Not Necessary	300.00 FL	*- FL
40	4		*RADIATOR MOUNTING	Not Necessary	100.00 FL	*- FL
41	1		*RADIATOR FAN COWLING	Cracked	352.00 FL	*244.50 FL
42	1		*RADIATOR FAN MOTOR	Not Working	364.00 FL	*364.00 FL
43	1		*RADIATOR FAN BLADE	Cracked	180.00 FL	*180.00 FL
44	1		*RADIATOR HOSE	Not Necessary	58.00 FL	*- FL
45	1		*RADIATOR TOP HOSE JOINT (T)	Twisted	69.00 FL	*69.00 FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*RADIATOR LOWER HOSE	Not Necessary	68.00 FL	*- FL
47	1		*BATTERY TOP BRACKET	Not Necessary	68.00 FL	*- FL
48	1		*BRACE PANEL	Bent	195.00 FL	*121.30 FL
49	1		*FRONT WIRE HARNESS	Not Necessary	1,458.50 FL	*- FL
50	2		*HEADLAMP	Cracked	5,970.00 FL	*4,700.00 FL
51	2		*HEADLAMP CHROME MOULDING	Not Necessary	250.00 FL	*- FL
52	2		*HEADLAMP TOP PANEL	Bent	430.00 FL	*308.24 FL
53	4		*HEAD LAMP LOWER BRACKET	Not Necessary	232.00 FL	*- FL
54	1		*FRONT AIR DUCT (FLEXIBLE PIPE)	Deformed	120.00 FL	*90.00 FL
55	1		*AIR CLEANER HOUSING	Cracked	512.00 FL	*395.00 FL
56	1		*ENGINE TOP COVER	Not Necessary	415.00 FL	*- FL
57	1		*ABS PUMP	Not Necessary	2,170.00 FL	*- FL
58	1		*HYBRID INVERTOR	Not Necessary	8,950.00 FL	*- FL
59	1		*HYBRID INVERTOR BRACKET	Not Necessary	159.00 FL	*- FL
60	1		*INTAKE MANIFOLD	Not Necessary	1,280.00 FL	*- FL
61	1		*INTERNATOR	Not Necessary	1,129.00 FL	*- FL
62	1		*FUSE BOX	Not Necessary	652.00 FL	*- FL
63	1		*AIRCON COMPRESSOR	Not Necessary	1,130.00 FL	*- FL
64	1		*SET ENGINE MOUNTING	Not Necessary	851.00 FL	*- FL
65	1		*WIPER WASHER TANK	Not Necessary	186.00 FL	*- FL
66	1		*WIPER WASHER TANK MOTOR	Not Necessary	212.00 FL	*- FL
67	1		*COOLANT RESERVOIR	Not Necessary	185.00 FL	*- FL
68	1		*RESONATOR BOX	Not Necessary	498.00 FL	*- FL
69	1		*FRONT DASHBOARD	Torn	2,985.00 FL	*1,411.80 FL
70	1		*FRONT DASHBOARD AIRBAG	Activated	698.00 FL	*698.00 FL
71	1		*STEERING AIBAG	Activated	698.00 FL	*698.00 FL
72	1		*DRIVER FOOT AIRBAG	Activated	698.00 FL	*698.00 FL
73	2		*FRONT SEAT BELT	Activated	1,680.00 FL	*1,680.00 FL
74	1		*FRONT DOOR	O/S Bent / N/S Not Necessary	2,250.00 FL	*1,125.00 FL
75	1		*REAR BUMPER	Deformed	698.00 FL	*542.00 FL
76	2		*REAR BUMPER SENSOR	Not Working	778.20 FL	*778.20 FL
77	2		*REAR BUMPER REFLECTOR	Not Necessary	170.00 FL	*- FL
78	1		*REAR BUMPER RETAINER	N/S Not Necessary/O/S Necessary	210.00 FL	*105.00 FL
79	1		*REAR BUMPER REINFORCEMENT	Bent	397.00 FL	*332.70 FL
80	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	224.00 FL	*224.00 FL
81	1		*AIR VENT	Not Necessary	65.80 FL	*- FL
82	1		*BOOTLID	Bent	989.00 FL	*838.90 FL
83	1		*BOOT LID INNER TRIM	Deformed	321.00 FL	*278.90 FL
84	2		*BOOTLID REFLECTOR C/W CHROME	Cracked	996.00 FL	*776.20 FL
85	4		*BOOTLID STOPPER	Necessary	300.00 FL	*128.00 FL
86	2		*BOOT LID HINGE	Not Necessary	424.00 FL	*- FL
87	1		*BOOTLID TOP LOCK	Bent	398.00 FL	*287.30 FL
88	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	312.00 FL	*- FL
89	1		*BOOTLID LOWER LOCK	Bent	40.00 FL	*40.00 FL
90	1		*BOOTLID WEATHERSTRIPE	Necessary	220.00 FL	*186.50 FL
91	1		*BOOTLID LOGO	Necessary	75.00 FL	*75.00 FL
92	1		*BOOTLID EMBLEM COROLLA	Necessary	65.00 FL	*65.00 FL
93	1		*BOOTLID EMBLEM ALTIS	Necessary	75.00 FL	*65.00 FL
94	1		*BOOTLID EMBLEM HYUNDAI	Necessary	68.00 FL	*68.00 FL
95	1		*BOOTLID SENSOR	Missing	312.00 FL	*280.00 FL
96	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	124.00 FL	*- FL
97	2		*TAILLAMP C/W CHROME	Scratched	1,596.00 FL	*1,224.00 FL
98	2		*TAILLAMP LOWER PANEL	Bent	640.00 FL	*640.00 FL
99	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	112.00 FL	*112.00 FL
100	1		*REAR FENDER	N/S Repair / O/S Buckled	2,048.00 FL	*980.20 FL
101	2		*REAR FENDER INNER COWLING	Not Necessary	716.00 FL	*- FL
102	2		*REAR FENDER INNER TRIM	Deformed	1,540.00 FL	*824.80 FL
103	2		*REAR DOOR WEATHERSTRIP	Not Necessary	396.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
104	2		*REAR DOOR INNER LOCK	Not Necessary	650.00 FL	*- FL
105	1		*REAR END PANEL	Buckled	695.00 FL	*695.00 FL
106	1		*REAR END PANEL TOP GARNISH	Deformed	280.00 FL	*280.00 FL
107	1		*REAR FLOOR PANEL	Buckled	1,025.00 FL	*937.00 FL
108	1		*REAR FLOOR PANEL TOP BOARD	Deformed	357.00 FL	*291.80 FL
109	1		*REAR FLOOR PANEL TOP TOOLS SPONGE	Cracked	398.00 FL	*148.60 FL
110	2		*REAR FLOOR SIDE PANEL	Not Necessary	624.00 FL	*- FL
111	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	251.00 FL	*- FL
112	1		*REAR EXHAUST PIPE	Not Necessary	956.00 FL	*- FL
113	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*35.00 FS
114	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
115	8		*FRONT BUMPER LOWER GRILLE CLIP	Necessary	52.00 FS	*30.00 FS
116	1		*FRONT BUMPER LOWER COVER GARNISH CLIP RH (6 PCS)	Necessary	39.00 FS	*20.00 FS
117	1		*FRONT BUMPER LOWER COVER GARNISH CLIP LH (6 PCS)	Necessary	39.00 FS	*20.00 FS
118	4		*FRONT RADIATOR GRILLE CLIP	Necessary	26.00 FS	*20.00 FS
119	1		*FRONT SUPPORT SEALANT	Not Necessary	80.00 FS	*- FS
120	1		*FRONT W/SCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
121	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*40.00 FS
122	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
123	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
124	1		*BATTERY	Cut	300.00 FS	*150.00 FS
125	1		*RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
126	10		*BOOT LID INSULATOR CLIP	Necessary	65.00 FS	*30.00 FS
127	4		*TAILLAMP CLIPS	Necessary	32.00 FS	*20.00 FS
128	2		*TAILLAMP PANEL SEALANT	Necessary (1 PCS ONLY)	120.00 FS	*30.00 FS
129	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
130	1		*REAR FENDER SEALANT	O/S Necessary	300.00 FS	*60.00 FS
131	1		*REAR WINDSCREEN INNER SEAL }	Necessary	50.00 FS	*60.00 FS
132	1		*REAR WINDSCREEN SEALANT }	Necessary	60.00 FS	*- FS
133	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
134	12		*REAR FENDER COWLING CLIPS (RH)	Necessary	78.00 FS	*30.00 FS
135	12		*REAR FENDER INNER TRIMD CLIPS	Not Necessary	78.00 FS	*- FS
136	1		*REAR END PANEL TOP GARNISH CLIPS (6 PCS)	Necessary	39.00 FS	*20.00 FS
137	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*40.00 FS
138	1		*REAR FLOOR PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
139	2		*REAR WHEEL HOUSING INSULATION SEAL	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	82,196.90	35,817.54
- List Item Discount on L Items 25.00/25.00% (\$)	19,804.73	8,760.64
Total Parts (\$)	62,392.17	27,056.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	1,200.00
3	WIRING CHECK	New	200.00	60.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	150.00	120.00
5	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	150.00	120.00
6	REMOVE AND REFIX FRONT DASHBOARD	New	400.00	180.00
7	RADIATOR PRESSURE TEST	New	60.00	40.00
8	RESET HYBRID TROUBLE CODE	New	600.00	0.00
9	REALIGN CHASSIS FRAME	New	250.00	80.00
10	REFOCUS HEADLAMP BEAM	New	60.00	20.00
11	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,800.00	1,400.00
12	TO SPRAY PAINT AFFECTED AREA	New	2,600.00	1,200.00
13	TUFF COAT	New	250.00	100.00
14	WIRING CHECK	New	80.00	60.00
15	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	300.00	80.00
16	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
17	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
18	REMOVE AND REFIX FUEL TANK	New	200.00	0.00
19	REAR CHASSIS ALIGNMENT	New	250.00	100.00
20	TRANSFER BOOTLID MECHANISM	New	60.00	40.00
21	CONDUCT WATER LEAKAGE TEST	New	100.00	30.00
Gross Labour Cost (S\$)			12,110.00	5,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >