



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 8200Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	DEFORMED / CUT	1,579.60	1,579.60
1	REAR BUMPER BRACKET RH (CONSISTENT)	NOT NECESSARY	143.20	-
1	REAR FENDER O/S (CONSISTENT)	TO REPAIR SEE LABOUR	2,005.10	-
1	REAR TAILLAMP RH (CONSISTENT)	SCRATCHED	638.00	605.00
	LESS 10% DISCOUNT		-	-218.46
			4,365.90	1,966.14
	<b><u>LABOUR</u></b>			
	LABOUR TO RENEW ALL ABOVE PARTS & KNOCK. INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		1,700.00	520.00
	LABOUR TO REFOCUS & RENEW TAIL LAMP.	NOT NECESSARY	380.00	-
	LABOUR TO RUST PROOFING.	NOT NECESSARY	280.00	-
	LABOUR TO SPRAY & PAINTING ON AFFECTED AREA.		1,200.00	400.00
			3,560.00	920.00
	<b>GRAND TOTAL</b>		<b>7,925.90</b>	<b>2,886.14</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,300.00</b>

Report Ref No. CS/ASM22009004/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.