



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 9939T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER PIECE (CONSISTENT)	DISTORTED	2,250.00	1,890.59
1	TOW HOOK (CONSISTENT)	NOT NECESSARY	100.00	-
1	RH RETAINER (CONSISTENT)	CRACKED	60.00	60.00
1	RH REAR TAIL LIGHT (CONSISTENT)	CRACKED	1,650.00	811.93
1	LOWER DIFFUSER (CONSISTENT)	TWISTED	450.00	450.00
1	LOWER DIFFUSER RETAINER (CONSISTENT)	NOT NECESSARY	150.00	-
1	KICKBOOT BRACKET (CONSISTENT)	NOT NECESSARY	200.00	-
1	RH EXHAUST PIPE (CONSISTENT)	NOT NECESSARY	650.00	-
1	RH EXHAUST PIPE BRACKET (CONSISTENT)	NOT NECESSARY	180.00	-
6	REAR SENSOR @\$250.00 (CONSISTENT)	NOT NECESSARY	1,500.00	-
	LESS 10% DISCOUNT		-	-321.25
			7,190.00	2,891.27
	<u>LABOUR</u>			
	LABOUR TO RECHECK SENSOR.		150.00	50.00
	PAINTING.		400.00	300.00
	LABOUR TO PANEL BEATING & REPLACED BUMPER.		300.00	300.00
			850.00	650.00
	GRAND TOTAL		8,040.00	3,541.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/ASM22009005/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.