10/20/22, 10:30 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB22009006/AVY3M4

**Date:** 20/10/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

Claimant Vehicle SJZ9259G Insured Vehicle No: SNF6538D

Date of Loss: 30/08/2022 Nature of Claim: TP Claim No: MFL2022D0004850

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJZ9259G

 Make & Model:
 MERCEDES-BENZ E250, 2.0 CGI (A)
 Engine No:
 27186030166429

 Reg. Date:
 06/01/2011 (Man. Year: 2010)
 Chassis No:
 WDD2120472A359311

Colour: White Odometer: 157551 km

Engine Capacity: 1796 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 265/35 R18 Rear Tyre Size: 265/35 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,590.30	3,880.04	710.26	15.47
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,400.00	630.00	770.00	55.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,990.30	4,510.04	1,480.26	24.71
	Approved Total (Overridden) (S\$)		3,600.00		
	Nett Amount (S\$)	5,990.30	3,600.00	2,390.30	39.90

**INSPECTION** 

Date Inspected:

Date of Assignment: 13/09/2022

8 KAKI BUKIT AVENUE 4, PREMIER@KAKI

15/09/2022 Inspected At:

SINGAPORE 415875

REPAIRER: 2020 SPRAY PAINTING PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Oct 2022)

Parts: 143 MERCEDES-BENZ E250 2.0 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJZ9259G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,640.60 F	*1,640.60 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Damaged	58.40 F	*58.40 FL
3	1		*REAR BUMPER TOW COVER	Deformed	55.90 F	*55.90 FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	485.10 F	*485.10 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	765.00 F	*765.00 FL
6	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	211.80 F	*- FL
7	2		*REVERSE SENSOR	Damaged	510.00 F	*510.00 FL
8	1		*TAILLAMP RH	Cracked	672.50 F	*672.50 FL
9	1		*TAILLAMP LOWER BRACKET RH	Cracked	68.10 F	*68.10 FL
10	1		*REAR FENDER AIR VENT	Not Necessary	72.90 F	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,590.30	4,305.60
			- List Item Discount o	on L Items 0.00/10.00% (S\$)	0.00	425.56
				Total Parts (S\$)	4,590.30	3,880.04
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	500.00	300.00
2	SPRAY PAINTING	New	600.00	250.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	0.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
		Gross Labour Cost (S\$)	1,400.00	630.00
	Report wa	as unsubmitted during this print-out.		

< END OF ESTIMATES >