

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22009007/TVY3Q2**Date:** 28/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276
Claimant Vehicle No :	SHC3089P	Insured Vehicle No :	SLR1305C
Date of Loss:	12/09/2022	Nature of Claim:	TP
		Claim No:	M2205002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3089P		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR2C06300
Reg. Date:	01/04/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU603079848
Colour:	Blue	Odometer:	545997 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,261.19	6,400.22	860.97	11.86
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,730.00	1,720.00	1,010.00	37.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,002.19	8,131.22	1,870.97	18.71
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	10,002.19	6,500.00	3,502.19	35.01
+ GST 7.00/7.00% (S\$)	700.15	455.00	245.15	35.01
Nett Amount (S\$)	10,702.34	6,955.00	3,747.34	35.01

INSPECTION

Date of Assignment:	13/09/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/09/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3089P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID COVER	Bent	1,303.29 FL	*1,303.29 FL
2	1		*GARNISH SUB - ASSY BACK DOOR OUTSIDE	Cracked	1,054.71 FL	*1,054.71 FL
3	1		*TRUNK LID EMBLEM - PRIUS	Necessary	62.14 FL	*62.14 FL
4	1		*TRUNK LID EMBLEM - HYBRID	Necessary	62.14 FL	*62.14 FL
5	1		*TRUNK LID EMBLEM - TOYOTA STAR	Necessary	81.43 FL	*81.43 FL
6	1		*TRUNK LID REAR WINDSCREEN GLASS (BIG)	Necessary	805.80 FL	*1,758.70 FL
7	1		*TRUNK LID REAR WINDSCREEN GLASS (SMALL)	Necessary	1,758.70 FL	*805.80 FL
8	1		*TRUNK LID REAR WINDSCREEN GLASS MOULDING	Necessary	40.40 FL	*40.40 FL
9	1		*REAR BUMPER ASSY	Cracked	503.04 FL	*503.04 FL
10	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1		*REAR BUMPER BEAM	Bent	378.32 FL	*378.32 FL
12	1		*REAR BUMPER CENTRE MOULDING	Deformed	654.96 FL	*654.96 FL
13	1		*COVER FLOOR UNDERCOVER	Deformed	220.50 FL	*220.50 FL
14	1		*REAR BUMPER TOW COVER	Missing	82.70 FL	*82.70 FL
15	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
16	1		*REVERSE SENSOR	Not Working	135.70 F	*135.70 F
17	1		*TAILLAMP ASSY UPPER LH	Cracked	557.90 FL	*557.90 FL
18	1		*TAILLAMP ASSY LOWER LH	Cracked	570.00 FL	*570.00 FL
19	1		*REAR END PANEL	Repair	738.96 FL	*- FL
20	1		*REAR END PANEL GARNISH	Not Necessary	165.80 FL	*- FL
21	1		*REAR NUMBER PLATE	Bent	50.00 F	*50.00 F
22	2		*WINDSCREEN SEALANT	Necessary	46.00 F	*46.00 F
23	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	94.80 FL	*- FL
24	1		*SEAL REAR BUMPER SIDE LH	Not Necessary	148.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **9,587.69** **8,439.73**
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,326.50 2,039.51

Total Parts (\$\$) **7,261.19** **6,400.22**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAYPAINT	New	1,000.00	750.00
3	TUFF KOTE	New	50.00	30.00
4	CHECK WIRING	New	50.00	30.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
7	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			2,730.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >