

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22009008/RVY3E2
Date: 10/03/2023**REFERENCE**

Insured/Claimant:	SRI MURUGAN TRADING PTE LTD	Policy No:	DMCG22000704
Date of Loss:	12/09/2022	Nature of Claim:	OD
		Claim No:	CDMCG22001894

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK9340C		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KDB068625
Reg. Date:	25/01/2021 (Man. Year: 2020)	Chassis No:	JTFAT35YX0K216252
Colour:	Grey	Odometer:	60561 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,593.15	4,847.81	8,745.34	64.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,440.00	1,580.00	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,613.15	6,287.81	10,325.34	62.15
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	15,313.15	4,987.81	10,325.34	67.43
+ GST 7.00/7.00% (S\$)	1,071.92	349.15	722.77	67.43
Nett Amount (S\$)	16,385.07	5,336.96	11,048.11	67.43

INSPECTION

Date of Assignment: 13/09/2022

Date Inspected: 14/09/2022 Inspected At:

William's Auto Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD 391-B YEW TEE
INDUSTRIAL ESTATE
Singapore 677965

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Mar 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9340C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL - LH	Scratched	296.45 F	*255.00 FL
2	1		*FRONT CORNER PANEL INNER BRACKET - LH	Bent	49.20 F	*49.20 FL
3	1		*FRONT GRILLE	Repair	393.20 F	*- FL
4	1		*FRONT GRILLE SEAL	Not Necessary	69.70 F	*- FL
5	1		*HEAD LAMPS - LH	Cracked	1,589.40 F	*727.10 FL
6	1		*HEAD LAMP LOWER SEAL - LH	Scratched	78.50 F	*48.50 FL
7	1		*FRONT DOOR V - LH	Buckled	985.20 F	*985.20 FL
8	1		*FRONT DOOR FRONT COVER GARNISH - LH	Not Necessary	96.80 F	*- FL
9	1		*FRONT DOOR RUBBER - LH	Necessary	245.70 F	*146.00 FL
10	1		*FRONT DOOR LOWER SEAL - LH	Necessary	96.90 F	*96.90 FL
11	1		*FRONT DOOR HINGE - LH	Bent	78.10 F	*78.10 FL
12	1		*FRONT DOOR LOCK - LH	Not Necessary	257.30 F	*- FL
13	1		*FRONT DOOR CATCH - LH	Not Necessary	96.50 F	*- FL
14	1		*FRONT DOOR CHECKER - LH	Not Necessary	98.70 F	*- FL
15	1		*FRONT DOOR INNER TRIMBOARD - LH	Deformed	698.60 F	*430.00 FL
16	1		*FRONT DOOR PILLAR OUTER - LH	Repair	497.80 F	*- FL
17	1		*FRONT DOOR PILLAR RUBBER - LH	Cut	239.20 F	*239.20 FL
18	1		*FRONT SIDE MIRROR STAY - LH	Not Necessary	479.20 F	*- FL
19	1		*FRONT SIDE MIRROR (BIG) - LH	Not Necessary	267.30 F	*- FL
20	1		*FRONT DOOR PILLAR COVER GARNISH - LH	Not Necessary	138.70 F	*- FL
21	1		*FRONT WHEEL ARCH PANEL SIDE SEAL - LH	Necessary	119.70 F	*119.70 FL
22	1		*FRONT FLOOR PANEL	Not Necessary	1,557.50 F	*- FL
23	1		*FRONT CABIN LOWER STEP GARNISH - LH	Cracked	214.90 F	*161.18 FL
24	1		*FRONT CABIN LOWER STEP OUTER PANEL - LH	Repair	247.40 F	*- FL
25	1		*FRONT BUMPER	Torn	423.90 F	*423.90 FL
26	1		*FROT BUMPER BRACKET	Bent	267.10 F	*138.00 FL
27	1		*FRONT BUMPER FOG LAMP COVER - LH	Cut	98.50 F	*98.50 FL
28	1		*AIR-CON LIQUID PIPE	Bent	297.20 F	*297.20 FL
29	1		*AIRCON DISCHARGE PIPE	Not Necessary	379.20 F	*- FL
30	1		*AIR CON CONDENSER FAN ASSY	Cracked	695.70 F	*695.70 FL
31	1		*AIRCON CONDENSER	Bent	1,078.60 F	*1,078.60 FL
32	1		*AIRCON CONDENSER BRACKET	Bent	289.10 F	*289.10 FL
33	1		*AIRCON RECEIVER DRIER	Not Necessary	197.40 F	*- FL
34	1		*FRONT WHEEL RIM - LH	Not Necessary	398.10 F	*- FL
35	1		*FRONT DOOR SIDE LETTERING / PANEL MARKER - LH	Necessary	20.00 FS	*20.00 FS
36	1		*SET FRONT DOOR INNER TRIMBOARD CLIPS - LH	Necessary	65.00 FS	*40.00 FS
37	1		*FRONT CABIN LOWER STEP GARNISH CLIPS - LH	Necessary	20.00 FS	*20.00 FS
38	1		*FRONT CABIN LOWER STEP INNER PANEL - LH	Repair	471.40 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **13,593.15** **6,437.08**
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,589.27

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	13,593.15
						4,847.81
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS, JACK, STRAIGHTEN, CUT, WELD, REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME	New	1,200.00	600.00
2	LABOUR TO TRANSFER DAMAGED FRONT DOOR - LH ATTACHMENTS TO NEW DOOR	New	80.00	60.00
3	LABOUR TO AIRCON JOB, CHECK, CHANGE PARTS AND REFILL GAS	New	180.00	120.00
4	TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS	New	1,200.00	600.00
5	LABOUR TO REMOVE UPHOLSTERY SEATS, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS	New	150.00	60.00
6	LABOUR TO REMOVE, CHECK UNDER CARRIAGE AND REPLACE NEW RIM	New	120.00	0.00
7	LABOUR TO CONDUCT 4XWHEEL ALIGNMENT	New	90.00	0.00
Gross Labour Cost (S\$)			3,020.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >