

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 12.09.2022

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **CB7646U**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 12.09.2022
TIME OF ACCIDENT : 06:25 HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP <i>crack</i>	2	\$ 380.00	\$ 760.00
2	TAILLAMP LOWER GARNISH <i>2x110</i>	2	\$ 135.00	\$ 270.00
3	TAILLAMP LOWER GARNISH RETAINER	2	\$ 65.00	\$ 130.00
4	REAR BUMPER <i>crack</i>	1	\$ 450.00	\$ 450.00
5	REAR BUMPER SIDE RETAINER <i>Not in</i>	2	\$ 98.10	\$ 196.20
6	TAILGATE <i>crack</i>	1	\$ 1,698.00	\$ 1,698.00
7	TAILGATE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
8	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
9	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 340.00	\$ 340.00
10	TAILGATE INNER TRIM <i>trim</i>	1	\$ 495.00	\$ 495.00
11	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 296.00	\$ 296.00
12	TAILGATE WEATHERSTRIP PROTECTOR <i>But</i>	1	\$ 198.00	\$ 198.00
13	TAILGATE INNER LOCK <i>crack</i>	1	\$ 420.00	\$ 420.00
14	TAILGATE LOWER LOCK <i>new</i>	1	\$ 35.00	\$ 35.00
15	TAILGATE DAMPER <i>new</i>	2	\$ 110.00	\$ 220.00
16	TAILGATE CORNER GARNISH LH <i>new</i>	1	\$ 21.00	\$ 21.00
17	REVERSE CAMERA <i>new</i>	1	\$ 1,314.60	\$ 1,314.60
18	REAR STEP PANEL <i>crack</i>	1	\$ 362.00	\$ 362.00
19	REAR END PANEL (EXTEND) LH <i>crack</i>	1	\$ 311.10	\$ 311.10
20	REAR END PANEL (OUTER) <i>crack</i>	1	\$ 425.00	\$ 425.00
21	REAR END PANEL (INNER) <i>Repair</i>	1	\$ 871.00	\$ 871.00
22	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,960.00	\$ 1,960.00
23	REAR SPARE TYRE HOLDER BRACKET <i>3x1</i>	1	\$ 380.00	\$ 380.00
24	REAR SPARE TYRE HOLDER BOLT <i>1x</i>	1	\$ 60.00	\$ 60.00

5264.10
3948.07

TOTAL PRICE \$ 11,320.90
LESS 25% \$ 2,830.23

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **CB7646U**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 12.09.2022
 TIME OF ACCIDENT : 06:25 HRS

SUB TOTAL PRICE \$ 8,490.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	TAILLAMP LOWER GARNISH CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
5	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
7	TAILGATE OUTER MOULDING STICKER 'EMERGENCY DOOR' <i>new</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
8	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00 <i>15</i>
9	TAILGATE STICKER 'AWC' <i>new</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
10	TAILGATE STICKER 'CHINESE WORDS' <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
11	TAILGATE STICKER 'HIACE' <i>new</i>	1	\$ 80.00	\$ 80.00 <i>25</i>
12	TAILGATE WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
13	TAILGATE WINDSCREEN GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
14	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>30</i>
15	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
16	REAR END PANEL (INNER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
17	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00 <i>+</i>
18	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>new</i>	1	\$ 480.00	\$ 480.00 <i>+</i>
19	REAR FLOOR PANEL MATT (SPECIAL TYPE) <i>new</i>	1	\$ 850.00	\$ 850.00 <i>+</i>
20	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00 <i>20</i>

TOTAL \$ 3,330.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,400.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>
4	TRANSFER TAILGATE MECHAISM	\$ 120.00	<i>60</i>
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **CB7646U**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 12.09.2022
 TIME OF ACCIDENT : 06:25 HRS

6	CONDUCT WATER LEAKAGE TEST	\$	120.00	X
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$	80.00	50
8	REMOVE AND REFIX REAR REVERSE CAMERA	\$	80.00	50
9	REMOVE AND REFIX CAR VIDEO RECORDER	\$	80.00	50
10	REMOVE AND REFIX LINING & SEATS	\$	500.00	80
11	REMOVE AND REFIX AND REWIRING TRIANGLE SIGN	\$	80.00	30
12	REAR CHASSIS ALIGNMENT	\$	250.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	160.00	X

TOTAL \$ 5,770.00

2070

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,820.68
 TOTAL LABOUR COST : \$ 5,770.00
 TOTAL REPAIR COST : \$ 17,590.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin L
 L/S 12/09/22

06 hrs

total: 6568.07

L/S: ~~52K~~
 5,250.00