

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009020/AQCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant:	ANKIT KHETAN	Policy No:	7220056111	
Date of Loss:	03/09/2022	Nature of Claim:	OD	Claim No: 0842514674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF3735X		
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A)	Engine No:	DEM031711
Reg. Date:	24/05/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF54MA039952
Colour:	Blue	Odometer:	1207 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$245,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,729.00	10,127.44	11,601.56	53.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	3,022.00	2,950.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,701.00	13,149.44	14,551.56	52.53
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	26,101.00	11,549.44	14,551.56	55.75
+ GST 8.00/8.00% (\$\$)	2,088.08	923.96	1,164.12	55.75
Nett Amount (\$\$)	28,189.08	12,473.40	15,715.68	55.75

INSPECTION

Date of Assignment:	14/09/2022	
Date Inspected:	13/09/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	293.00 FS	*234.00 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	1		*RADIATOR AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
8	1		*RADIATOR AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER OUTER GRILLE HOLE COVER - RH	Not Necessary	54.00 FS	*- FS
10	1		*RADIATOR GRILLE TRIM - CENTER	Not Necessary	127.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	1,881.00 FS	*- FS
12	1		*RADIATOR GRILLE CAP COVER	Not Necessary	141.00 FS	*- FS
13	1		*RADIATOR GRILLE BRACKET	Not Necessary	19.00 FS	*- FS
14	1		*FRONT CAMERA	Not Necessary	1,264.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS
17	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
20	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
21	1		*LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
22	2		*FRONT BUMPER SUPPORT - LH	Not Necessary	64.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	532.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	449.00 FS	*- FS
26	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
27	1		*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
28	1		*FRONT FENDER - RH	Dented	1,189.00 FS	*951.20 FS
29	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
30	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	83.00 FS	*- FS
31	1		*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
32	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
33	1		*FRONT FENDER BRACE - RH	Not Necessary	132.00 FS	*- FS
34	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
35	1		*FRONT FENDER TRIM - RH	Deformed	171.00 FS	*136.40 FS
36	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	299.00 FS	*- FS
37	1		*FRONT WHEEL SPOILER - RH	Torn	82.00 FS	*65.12 FS
38	1		*FRONT STONE CHIP GUARD - RH	Not Necessary	57.00 FS	*- FS
39	1		*FRONT SPOILER END PLATE - RH	Not Necessary	40.00 FS	*- FS
40	1		*HEADLIGHT - RH	Cut	8,172.00 FS	*6,537.60 FS
41	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
42	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
43	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
44	1		*RADIATOR AIR DUCT - RH	Not Necessary	36.00 FS	*- FS
45	1		*RADIATOR AIR DUCT - RH	Not Necessary	19.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
48	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
49	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
50	1		*HEADLIGHT COVER - RH UPPER (Supplementary)	Deformed	49.00 FS	*38.64 FS
51	1		*FRONT FENDER TOP COVER - RH (Supplementary)	Deformed	40.00 FS	*31.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,729.00 10,127.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,972.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >