2/18/23, 11:04 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III22009033/UPA3Q2

Date: 18/02/2023

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle GBC9415M Insured Vehicle No: YQ3311Y

No: GBC9413W Illistred Verlicle No. 1 Q33111

Date of Loss: 13/09/2022 Nature of Claim: TP Claim No: MFL2022D0005040

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC9415M

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M) Engine No: 1KD2376936

Reg. Date: 19/03/2014 (Man. Year: 2014) Chassis No: JTFHT02P300134710

Colour: White Odometer: 171131 km

Engine Capacity: 2982 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,070.80	1,904.87	5,165.93	73.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,780.00	1,620.00	1,160.00	41.73
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,850.80	3,524.87	6,325.93	64.22
	Approved Total (Overridden) (S\$)		2,800.00		
	Nett Amount (S\$)	9,850.80	2,800.00	7,050.80	71.58
	+ Loss of Use (4.0 x S\$1	00.00/day) (S\$)	400.00		
		(S\$)	3,200.00		
	Liable Amour	nt (50.00%) (S\$)	1,600.00		
	+ Doc/S	Search Fee (S\$)	7.45		
	Nett Liability (S\$)		1,607.45		
	Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 14/09/2022

Choo Motor Spray Painter (HQ)

Date Inspected: 14/09/2022 Inspected At: 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Oct 2022)

Parts: TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0) 213

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC9415M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,159.10 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	68.10 F	*68.10 FL
3	1		*TAILGATE HIACE EMBLEM	Not Necessary	80.50 F	*- FL
4	1		*TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
5	1		*REAR BUMPER	Repair	681.00 F	*- FL
6	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	105.00 F	*- FL
7	1		*REAR BUMPER CLIPS	Not Necessary	50.00 F	*- FL
8	1		*TAILLAMP O/S	Cracked	488.50 F	*368.10 FL
9	1		*TAILLAMP LOWER GARNISH O/S	Not Necessary	180.20 F	*- FL
10	1		*TAILLAMP LOWER GARNISH BRACKET O/S	Not Necessary	100.30 F	*- FL
11	1		*TAILLAMP HOUSING PANEL O/S	Dented / Cracked	482.50 F	*445.10 FL
12	1		*REAR END PANEL OUTER	Repair	650.10 F	*- FL
13	1		*REAR FENDER O/S	Dented / Cracked	2,010.50 F	*1,645.20 FL
F=Fra	nchise	part. S=SpcN	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	7,070.80	2,536.50
	- List Item Discount on L Items 0.00/25.00% (S\$)			0.00	631.63	
				Total Parts (S\$)	7,070.80	1,904.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO SPRAY RUST PROOFING	New	100.00	50.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	900.00
7	TO PUTTY & SPRAY PAINTING	New	1,100.00	650.00
		Gross Labour Cost (S\$)	2,780.00	1,620.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >