

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009044/APA3Q2**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800091233
Claimant Vehicle No :	EH1514B	Insured Vehicle No :	SMC9932G
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	5113047676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EH1514B	Engine No:	DEM028718
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF55MA018821
Reg. Date:	18/03/2021 (Man. Year: 2020)	Odometer:	9531 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,695.00	6,937.20	12,757.80	64.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,252.00	3,052.00	10,200.00	76.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,947.00	9,989.20	22,957.80	69.68
+ GST 8.00/8.00% (S\$)	2,635.76	799.14	1,836.62	69.68
Nett Amount (S\$)	35,582.76	10,788.34	24,794.42	69.68
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,290.34		

INSPECTION

Date of Assignment:	20/09/2022		Premium Automobiles Pte Ltd (HQ)
Date Inspected:	20/09/2022	Inspected At:	55 UBI ROAD 1
			Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Necessary	79.00 FS	*63.20 FS
3	1		*FRONT BUMPER GRILLE -CENTER	Cracked	219.00 FS	*174.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	72.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	293.00 FS	*234.00 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER TRIM -RH	Not Necessary	54.00 FS	*- FS
10	1		*FRONT BUMPER TRIM -CENTER	Not Necessary	127.00 FS	*- FS
11	1		*RADIATOR GRILLE	Deformed	1,881.00 FS	*1,504.80 FS
12	1		*RADIATOR GRILLE BRACKET	Not Necessary	19.00 FS	*- FS
13	1		*RADIATOR GRILLE SECURING PLATE	Not Necessary	12.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM BRACKET -RH	Not Necessary	254.00 FS	*- FS
17	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
20	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
21	1		*LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
22	2		*LOCK CARRIER BRACKET SUPPORT -RH/LH	Not Necessary	64.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR -INNER /OUTER	Not Necessary	532.00 FS	*- FS
24	1		*SET FRONT BUMPER WIRING	Not Necessary	449.00 FS	*- FS
25	1		*HORN LOW TONE -RH	Not Necessary	139.00 FS	*- FS
26	1		*HORN BRACKET -RH	Not Necessary	33.00 FS	*- FS
27	1		*FRONT FENDER -RH	Not Necessary	1,189.00 FS	*- FS
28	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
29	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	83.00 FS	*- FS
30	1		*FRONT FENDER BRACKET -RH	Not Necessary	41.00 FS	*- FS
31	1		*FRONT FENDER BRACE -RH	Not Necessary	132.00 FS	*- FS
32	6		*FRONT FENDER RIVET	Not Necessary	23.00 FS	*- FS
33	1		*FRONT FENDER CHROME TRIM -RH	Not Necessary	171.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	299.00 FS	*- FS
35	1		*FRONT WHEEL SPOILER -RH	Not Necessary	82.00 FS	*- FS
36	1		*FRONT WHEEL SPOILER TRIM -RH	Not Necessary	40.00 FS	*- FS
37	1		*FRONT FENDER STONE CHIP GUARD -RH	Not Necessary	57.00 FS	*- FS
38	1		*FRONT FENDER LOWER BRACKET -RH	Not Necessary	27.00 FS	*- FS
39	1		*FRONT FENDER TOP LEDGE COVER -RH	Not Necessary	40.00 FS	*- FS
40	1		*FRONT FENDER LEDGE COVER -RH	Not Necessary	18.00 FS	*- FS
41	1		*HEADLIGHT COVER -RH	Not Necessary	49.00 FS	*- FS
42	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
43	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
44	3		*BONNET IMPACT PROTECTION -LH/RH/CENTER	Necessary	62.00 FS	*73.20 FS
45	1		*BONNET SOUND ABSORBER	Not Necessary	382.00 FS	*- FS
46	1		*BONNET STRIKER -RH	Not Necessary	56.00 FS	*- FS
47	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE -CENTER	Not Necessary	64.00 FS	*- FS
49	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
50	1		*LOCK CARRIER	Not Necessary	1,478.00 FS	*- FS
51	1		*LOCK CARRIER SUPPORT -RH	Not Necessary	43.00 FS	*- FS
52	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
53	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
54	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
55	6		*READY -MIX COOLANT	Not Necessary	297.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR AIR DUCT -RH	Not Necessary	36.00 FS	*- FS
57	1		*RADIATOR AIR DUCT -RH	Not Necessary	19.00 FS	*- FS
58	1		*RADIATOR AIR GUIDE -UPPER	Not Necessary	19.00 FS	*- FS
59	1		*RADIATOR AIR GUIDE -LOWER	Not Necessary	25.00 FS	*- FS
60	1		*FRONT NO PLATE	Necessary	100.00 FS	*100.00 FS
61	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					19,695.00	6,937.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER ,CHARGE AIR COOLER AND RADIATOR ,CHECK ELECTRICAL FANS AND CONTROL UNIT ,PRESSURISE COOLING SYSTEM	New	1,600.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
6	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND BONNET	New	3,500.00	1,100.00
7	TO APPLY LTA APPROVAL FOR REMOVE AND RENEW OPC SEAL	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			13,252.00	3,052.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >