

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009047/UWY3Q2
Date: 19/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00012082200
Claimant Vehicle No :	SNB8273A	Insured Vehicle No :	SMW8421R
Date of Loss:	06/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206384/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB8273A	Engine No:	P520364458
Make & Model:	MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)	Chassis No:	JM6DJ2HAA01100929
Reg. Date:	14/11/2016 (Man. Year: 2016)	Odometer:	57549 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,661.12	5,135.28	525.84	9.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	2,140.00	1,050.00	32.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,851.12	7,275.28	1,575.84	17.80
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	8,851.12	5,800.00	3,051.12	34.47
+ GST 7.00/7.00% (S\$)	619.58	406.00	213.58	34.47
Nett Amount (S\$)	9,470.70	6,206.00	3,264.70	34.47

INSPECTION

Date of Assignment:	17/10/2022	
Date Inspected:	03/10/2022	Inspected At: SME Motor Pte Ltd (HQ) 1 KAKI BUKIT AVE6, #02-15 Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2022)**Parts:** 144 MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SNB8273A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Badly Dented	295.80 FL	*295.80 FL
2	1		*FRT LH FENDER INNER COWLING	Distorted	15.50 FL	*15.50 FL
3	1		*SET INNER COWLING CLIPS	Necessary	55.00 FL	*55.00 FL
4	1		*FRT LH DOOR	Dented / Bent	1,109.30 FL	*1,109.30 FL
5	1		*FRT DOOR TOP STICKER	Necessary	38.90 FL	*38.90 FL
6	1		*REAR LH DOOR	Dented / Bent	956.80 FL	*956.80 FL
7	1		*REAR LH DOOR STICKER	Necessary	38.90 FL	*38.90 FL
8	1		*LH ROCKER PANEL	Dented / Bent	658.80 FL	*658.80 FL
9	1		*FRT LH SPORT RIM	Warped	1,254.50 FL	*1,254.50 FL
10	1		*FRT LH SHOCK ABSORBER	Not Necessary	268.50 FL	*- FL
11	1		*FRT LH LOWER ARM	Not Necessary	388.80 FL	*- FL
12	1		*FRT LH KNUCKLE ARM	Bent	315.30 FL	*315.30 FL
13	1		*FRT LH KNUCKLE BEARING	Necessary	425.80 FL	*425.80 FL
14	1		*REAR SPORT RIM RH	Cut	1,254.50 FL	*1,254.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	7,076.40	6,419.10
- List Item Discount on L Items 20.00/20.00% (\$)	1,415.28	1,283.82
Total Parts (\$)	5,661.12	5,135.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX CUSHION AND SEATS	New	180.00	0.00
3	WHEEL ALIGNMENT	New	80.00	80.00
4	TRANSFER 2 DOORS COMPONENT FROM OLD TO NEW	New	300.00	120.00
5	REMOVE & REFIX FRT UNDERCARRIAGE	New	200.00	120.00
6	LABOUR CHARGE	New	1,200.00	800.00
7	SPRAY PAINTING	New	1,200.00	1,000.00
			Gross Labour Cost (\$\$)	3,190.00
				2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >