

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009048/UQY3Q2**Date:** 24/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00113232100

**Claimant Vehicle  
No :** FBP7935Z**Insured  
Vehicle No :** YQ4395Z

Date of Loss: 09/09/2022

Nature of Claim: TP

Claim  
No: SNM22D206448/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBP7935Z**

Make &amp; Model: HONDA NC750XA, 745cc

Engine No: RC88E5202270

Reg. Date: 13/06/2019 (Man. Year: 2019)

Chassis No: JH2RC90AXKK301918

Colour: Red

Odometer: 44793 km

Engine Capacity: 745 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,031.00	4,196.90	4,834.10	53.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	460.00	240.00	34.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,731.00</b>	<b>4,656.90</b>	<b>5,074.10</b>	<b>52.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	681.17	325.98	355.19	52.14
<b>Nett Amount (S\$)</b>	<b>10,412.17</b>	<b>4,982.88</b>	<b>5,429.29</b>	<b>52.14</b>

**INSPECTION**

Date of Assignment: 14/09/2022

Date Inspected: 14/09/2022

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Nov 2022)	
<b>Parts:</b>	N/A	HONDA NC750XA 745cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBP7935Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R381C CANDY CHROMOSPHERE RED (SIDE COVER)	Cracked	383.00 F	*383.00 FL
2	1		*R381C CANDY CHROMOSPHERE RED (SIDE COVER)	Cracked	383.00 F	*383.00 FL
3	1		*ALIGNMENT BODY/FRAME	Not Necessary	420.00 F	*- FL
4	1		*BOX REAR (SHAD) SH39	Grazed	455.00 F	*350.00 FL
5	1		*BOX SIDE (SHAD) SH23	Grazed	630.00 F	*630.00 FL
6	1		*BRACKET BOX REAR (SHAD)	Grazed	630.00 F	*630.00 FL
7	1		*BRACKET SIDE BOX 3P	Bent / Twisted	700.00 F	*700.00 FL
8	1		*CHAIN DRIVE ASSY (520-120)	Not Necessary	255.00 F	*- FL
9	1		*COVER CENTER SEAT	Not Necessary	84.00 F	*- FL
10	1		*FENDER REAR B	Distorted	362.00 F	*362.00 FL
11	1		*GASKET MUFFLER	Not Necessary	24.00 F	*- FL
12	1		*LABEL CHAIN ADJUSTER	Not Necessary	26.00 F	*- FL
13	1		*LAMP SIGNAL REAR LH	Cut	182.00 F	*182.00 FL
14	1		*LAMP SIGNAL REAR RH	Cut	182.00 F	*182.00 FL
15	1		*LIGHT ASSY LICENSE	Broken	104.00 F	*104.00 FL
16	1		*MUDGUARD REAR	Distorted	138.00 F	*138.00 FL
17	1		*MUFFLER COMP	Repair	840.00 F	*- FL
18	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	26.00 FS	*20.00 FS
19	1		*PLUG HOLE	Necessary	10.00 F	*10.00 FL
20	1		*PLUG HANDLE COVER (LOWER)	Necessary	10.00 F	*10.00 FL
21	2		*RIVET	Necessary	12.00 F	*12.00 FL
22	1		*RUBBER MOUNT LAMP SIGNAL LH	Necessary	42.00 F	*42.00 FL
23	1		*RUBBER MOUNT LAMP SIGNAL RH	Necessary	42.00 F	*42.00 FL
24	2		*RUBBER TAILLIGHT	Necessary	24.00 F	*24.00 FL
25	1		*SWINGARM SUB ASSY	Repair	2,334.00 F	*- FL
26	1		*TAIL LIGHT ASSY	Broken	319.00 F	*319.00 FL
27	1		*TYRE 160/60-17 (PIRELLI) ROSSO 3	Serviceable	276.00 F	*- FL
28	1		*BRACKET MUDGUARD REAR	Cracked	138.00 F	*138.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,031.00</b>	<b>4,661.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	464.10
<b>Total Parts (\$)</b>	<b>9,031.00</b>	<b>4,196.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2	New	70.00	60.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	630.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>700.00</b>	<b>460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >