

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009049/TPA3Q2**Date:** 19/02/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	OCL2022JM6BP2SAAM1109348TW2506		
Claimant Vehicle No :	SMQ5235M	Insured Vehicle No :	SND4086P		
Date of Loss:	06/09/2022	Nature of Claim:	TP	Claim No:	OWAISCL2022-0000152

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5235M		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B25511149
Reg. Date:	22/11/2019 (Man. Year: 2019)	Chassis No:	MRHFC5650KT001045
Colour:	Grey	Odometer:	14314 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,473.60	719.20	1,754.40	70.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	430.00	800.00	65.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,703.60	1,149.20	2,554.40	68.97
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/09/2022		
Date Inspected:	14/09/2022	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5235M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	646.00 FL	*646.00 FL
2	1		*FRONT BUMPER RETAINER RH	Necessary	38.00 FL	*38.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	540.00 FL	*- FL
5	1		*FOGLAMP RH	Not Necessary	470.00 FL	*- FL
6	1		*FOGLAMP GARNISH RH	Cut	165.00 FL	*165.00 FL
7	1		*HEADLAMP RH	Not Necessary	1,050.00 FL	*- FL
8	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	60.80 FL	*- FL
9	1		*FRONT FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	72.20 FL	*- FL
					Sub Total (\$\$)	3,092.00 899.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	618.40 179.80
					Total Parts (\$\$)	2,473.60 719.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	600.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	200.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (S\$)			1,230.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >