

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009051/AQY3E2
Date: 14/02/2023

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00007502202
Claimant Vehicle No :	SMU2946T	Insured Vehicle No :	PC3442H
Date of Loss:	07/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206407/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU2946T		
Make & Model:	NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR (A)	Engine No:	MR20862908B
Reg. Date:	18/06/2016 (Man. Year: 2016)	Chassis No:	JN1JANT32Z0001992
Colour:	Black	Odometer:	111478 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,518.00	6,601.90	8,916.10	57.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,460.00	1,440.00	49.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,418.00	8,061.90	10,356.10	56.23
Approved Total (Overridden) (S\$)		6,450.00		
Nett Amount (S\$)	18,418.00	6,450.00	11,968.00	64.98

INSPECTION

Date of Assignment:	14/09/2022	
Date Inspected:	15/09/2022 Inspected At:	Detail Lab (Kaki Bukit) 8 Kaki Bukit Avenue 4, #02-03/04 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2023)
Parts: M1-SUV	NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMU2946T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SET LH H/LAMP ASSY	Cracked	3,315.00 F	*2,642.00 FL	
2	1		*BONNET ASSY	Repair	1,356.00 F	*- FL	
3	1		*LH FENDER ASSY	Dented	750.00 F	*642.00 FL	
4	1		*LH RETAINER	Damaged	66.00 F	*66.00 FL	
5	1		*FRT BUMPER ASSY	Deformed	695.00 F	*695.00 FL	
6	1		*FRT LH WHEEL ARCH PROTECTOR	Deformed	226.00 F	*226.00 FL	
7	1		*FRT LH WHEEL COWLING	Deformed	215.00 F	*215.00 FL	
8	1		*LH FOGLAMP COVER	Not Necessary	175.00 F	*- FL	
9	1		*LH FOGLAMP	Cracked	195.00 F	*195.00 FL	
10	1		*BUMPER UNDER SPOILER	Not Necessary	285.00 F	*- FL	
11	1		*TOW HOOK COVER	Not Necessary	75.00 F	*- FL	
12	1		*RADIATOR GRILLE	Cracked	480.00 F	*480.00 FL	
13	1		*FRONT IMPACT SENSOR	Not Necessary	930.00 F	*- FL	
14	1		*LH HEADLAMP BRACKET	Damaged	95.00 F	*95.00 FL	
15	1		*RADIATOR TOP COVE SUPPORT	Repair	295.00 F	*- FL	
16	1		*AIR INTAKE SNORKEL INLET HOSE	Not Necessary	128.00 F	*- FL	
17	1		*FRT LH HUB/BEARING	Damaged	425.00 F	*425.00 FL	
18	1		*FRT LH WHEEL KNUCKLE	Not Necessary	787.00 F	*- FL	
19	1		*FRT LH LOWER CONTROL ARM	Bent	295.00 F	*295.00 FL	
20	1		*FRT LH SHOCK ABSORBER	Not Necessary	585.00 F	*- FL	
21	1		*FRT LH TYRE MUD FLAP	Not Necessary	125.00 F	*- FL	
22	1		*NISSAN EMBLEM	Not Necessary	85.00 FS	*- FS	
23	1		*235/60/R18	Not Necessary	330.00 FS	*- FS	
24	1		*NISSAN R18 SPORT RIM	Cut	1,685.00 FS	*580.00 FS	
25	1		*SET NUMBER PLATE	Not Necessary	50.00 FS	*- FS	
26	1		*FRT SPONGE	Cracked	95.00 F	*95.00 FL	
27	1		*AIR INTAKE SNORKEL (LOWER)	Deformed	185.00 F	*185.00 FL	
28	1		*FRT BUMPER LOWER GRILLE	Deformed	175.00 F	*175.00 FL	
29	1		*FRONT CAMERA	Not Necessary	985.00 F	*- FL	
30	1		*FENDER BRACKET	Bent	85.00 F	*85.00 FL	
31	1		*PWI STEERING RACK BELLOW LH	Not Necessary	75.00 F	*- FL	
32	1		*SET TIE ROD END LH	Not Necessary	95.00 F	*- FL	
33	1		*FUSE BOX BRACKET	Bent	175.00 F	*175.00 FL	
					Sub Total (\$\$)	15,518.00	7,271.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	669.10
					Total Parts (\$\$)	15,518.00	6,601.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	CHECK WIRING	New	120.00	30.00
4	UNDERCARRIAGE LABOUR	New	450.00	150.00
5	WHEEL ALIGNMENT	New	130.00	80.00
			Gross Labour Cost (\$\$)	2,900.00
				1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >