

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009062/RPA3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002119964
Claimant Vehicle No :	SMN9551P	Insured Vehicle No :	SLC4897U
Date of Loss:	13/09/2022	Nature of Claim:	TP
		Claim No:	202222006735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9551P	Engine No:	2ZR0C98446
Make & Model:	TOYOTA VOXY HYBRID, 1.8 V CVT (A)	Chassis No:	ZWR800364769
Reg. Date:	02/09/2019 (Man. Year: 2018)	Odometer:	203941 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,361.05	3,094.80	13,266.25	81.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	1,460.00	2,910.00	66.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,731.05	4,554.80	16,176.25	78.03
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	20,731.05	3,600.00	17,131.05	82.63
+ GST 7.00/7.00% (S\$)	1,451.17	252.00	1,199.17	82.63
Nett Amount (S\$)	22,182.22	3,852.00	18,330.22	82.63
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		33.00		
Nett Liability (S\$)		4,365.00		

INSPECTION

Date of Assignment:	14/09/2022	60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 Repairer: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
Date Inspected:	15/09/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 V CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN9551P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,458.00 FL	*1,712.00 FL
2	1		*TAILGATE LOCK	Not Necessary	640.00 FL	*- FL
3	1		*TAILGATE OUTER CHROME MOULDING C/W SWITCH	Not Necessary	512.00 FL	*- FL
4	1		*REAR TAILGATE OUTER CHROME MOULDING LOGO	Not Necessary	112.00 FL	*- FL
5	1		*REAR TAILGATE EMBLEM HYBRID	Necessary	80.00 FL	*80.00 FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	896.00 FL	*620.00 FL
7	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	98.40 FL	*98.40 FL
8	1		*REAR TAILGATE WEATHERSTRIPE	Necessary	287.00 FL	*287.00 FL
9	1		*REAR BUMPER	Deformed	720.00 FL	*580.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Not Necessary	318.00 FL	*- FL
11	1		*REAR BUMPER TOP CHROME MOULDING	Not Necessary	172.00 FL	*- FL
12	2		*REAR BUMPER BRACKET	Not Necessary	320.00 FL	*- FL
13	1		*REAR BUMPER TOW COVER	Missing	64.00 FL	*64.00 FL
14	1		*REAR END PANEL CENTER	Not Necessary	680.00 FL	*- FL
15	1		*REAR END PANEL INNER	Not Necessary	512.00 FL	*- FL
16	1		*REAR END PANEL OUTER	Not Necessary	622.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	345.00 FL	*345.00 FL
18	1		*REAR SPARE TYRE COMPARTMENT PANEL	Not Necessary	1,156.00 FL	*- FL
19	1		*REAR SPARE TYRE COMPARTMENT CARPET	Not Necessary	432.00 FL	*- FL
20	1		*REAR FLOOR PANEL	Not Necessary	1,598.00 FL	*- FL
21	1		*REAR TOOLS BOX	Not Necessary	320.00 FL	*- FL
22	1		*REAR TOOLS BOX TOP COVER	Not Necessary	1,280.00 FL	*- FL
23	2		*REAR TOOLS BOX TOP SIDE COVER	Not Necessary	1,088.00 FL	*- FL
24	1		*REAR TOOLS BOX REAR TOP GARNISH	Not Necessary	272.00 FL	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	2,688.00 FL	*- FL
26	1		*REAR AIR CON COOLING COIL ASSY	Not Necessary	2,511.00 FL	*- FL
27	1		*TAILGATE SENSOR	Cracked	220.00 FL	*220.00 FL
28	1		*SET REAR REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
29	1		*SET REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
30	2		*SET BOTH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	160.00 FS	*- FS
31	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*40.00 FS
32	2		*REAR WINDSCREEN GLASS PDVL DECADE STICKER	Not Necessary	60.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
34	1		*SET REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
35	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
Sub Total (\$\$)						21,461.40 4,096.40
- List Item Discount on L Items 25.00/25.00% (\$\$)						5,100.35 1,001.60
Total Parts (\$\$)						16,361.05 3,094.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	200.00	0.00
2	TO REMOVE AND REFIT REVERSE SENSOR /CAMERA	New	150.00	60.00
3	REMOVE AND REFIX REAR UPHOLSTERY	New	300.00	0.00
4	REPAIR AND STRAIGHTEN EXHAUST PIPE	New	250.00	0.00
5	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	New	150.00	60.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
7	CHECK AND RESET FAULT CODE LIGHT ON	New	300.00	80.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	300.00	40.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
10	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
Gross Labour Cost (S\$)			4,370.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >