

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009069/EVY3Q2
Date: 19/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00045602200
Claimant Vehicle No :	GQ8888E	Insured Vehicle No :	YQ6220G
Date of Loss:	31/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D206277/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GQ8888E	Engine No:	2GD4050698
Make & Model:	TOYOTA HILUX, 2.4 D G DOUBLE CAB (A)	Chassis No:	MROCB8DD200451855
Reg. Date:	03/02/2016 (Man. Year: 2015)	Odometer:	123996 km
Colour:	Grey		
Engine Capacity:	2393 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/80 R16	Rear Tyre Size:	215/80 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	527.50	517.50	10.00	1.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	460.00	560.00	54.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,547.50	977.50	570.00	36.83
Approved Total (Overridden) (S\$)		800.00		
	(S\$)	1,547.50	800.00	747.50
	+ GST 7.00/7.00% (S\$)	108.33	56.00	52.33
	Nett Amount (S\$)	1,655.83	856.00	799.83

INSPECTION

Date of Assignment:	15/09/2022	
Date Inspected:	13/10/2022	Inspected At: Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80 Singapore 159723
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Oct 2022)	
Parts:	N/A	TOYOTA HILUX 2.4 D G DOUBLE CAB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GQ8888E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Dented	650.00 FL	*650.00 FL	
2	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS	
					Sub Total (\$\$)	690.00	680.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	162.50	162.50
					Total Parts (\$\$)	527.50	517.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	300.00	200.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	500.00	200.00
3	ANTI RUST TREATMENT	New	100.00	30.00
4	CHECK WIRING SYSTEM & LIGHT	New	120.00	30.00
			Gross Labour Cost (\$\$)	1,020.00
				460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >