

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009081/UVY3Q2**Date:** 13/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00128502100

Claimant Vehicle No : SLF5848P**Insured Vehicle No :** XE5284D

Date of Loss: 12/09/2022

Nature of Claim: TP

Claim No: SNM22D206513/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLF5848P**

Make & Model: NISSAN SYLPHY, 1.5 (A)

Engine No: HR16993438B

Reg. Date: 31/08/2016 (Man. Year: 2016)

Chassis No: MNTBBAB17Z0027933

Colour: Blue

Odometer: 174504 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,012.45	10,759.62	14,252.83	56.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	2,540.00	3,940.00	60.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,492.45	13,299.62	18,192.83	57.77
Approved Total (Overridden) (\$\$)		10,600.00		
Nett Amount (\$\$)	31,492.45	10,600.00	20,892.45	66.34

INSPECTION

Date of Assignment: 14/09/2022

Date Inspected: 15/09/2022 Inspected At:

Galaxy Autocare Pte Ltd (HQ)
13 Kaki Bukit Road 4 #01-23 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF5848P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ABSORBER	O/S Bent	1,250.00 FL	*411.70 FL
2	1		*WHEEL BEARING	O/S Damaged	926.00 FL	*366.50 FL
3	1		*LOWER ARM	O/S Twisted	825.00 FL	*402.00 FL
4	2		*UPPER ARM	No such part	925.00 FL	*- FL
5	1		*STEERING RACK	Bent / Twisted	1,855.00 FL	*1,715.00 FL
6	1		*TURN INDICATOR RH	Scratched	85.00 FL	*52.50 FL
7	1		*SET FRONT SIDE MIRROR RH	Cracked	858.00 FL	*650.00 FL
8	1		*FRONT BUMPER	Repair	757.00 FL	*- FL
9	1		*FRONT FENDER RH	Dented / Bent	573.00 FL	*573.00 FL
10	1		*FORNT DOOR RH	Dented / Bent	1,582.30 FL	*961.40 FL
11	1		*FORNT DOOR HANDLE RH	Grazed	225.00 FL	*166.80 FL
12	1		*FORNT DOOR HANDLE INTERIOR RH	Not Necessary	175.00 FL	*- FL
13	1		*FRONT DOOR LOCK RH	Dented / Shorted	375.00 FL	*241.50 FL
14	2		*FRONT DOOR HINGE	Twisted	150.00 FL	*150.00 FL
15	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	285.00 FL	*118.00 FL
16	1		*FRONT DOOR CHROME MOULDING	Scratched	275.00 FL	*165.00 FL
17	1		*FRONT DOOR POWER WINDOW MOTOR	Bent / Jammed	577.00 FL	*390.00 FL
18	1		*FRONT DOOR POWER WINDOW SWITCH	Not Necessary	385.00 FL	*- FL
19	1		*FRONT DOOR POWER WINDOW	No such part	325.90 FL	*- FL
20	1		*FRONT DOOR INNER TRIMBOARD	Deformed / Torn	825.80 FL	*641.00 FL
21	1		*FRONT DOOR WINDOW GLASS O/S	Cut	375.00 FL	*375.00 FL
22	1		*ROCKER PANEL RH	Repair	925.10 FL	*- FL
23	1		*BODY SIDE ASSEMBLY	No such part	3,225.50 FL	*- FL
24	1		*REAR FENDER RH	Dented / Bent	1,725.00 FL	*1,425.00 FL
25	1		*REAR DOOR RH	Dented / Bent	1,324.80 FL	*985.20 FL
26	1		*REAR DOOR HANDLE RH	Grazed	225.00 FL	*166.80 FL
27	1		*REAR DOOR HANDLE INTERIOR RH	Not Necessary	175.00 FL	*- FL
28	2		*REAR DOOR HINGE	Bent / Twisted	150.00 FL	*150.00 FL
29	1		*REAR DOOR WEATHERSTRIP RH	Necessary	285.00 FL	*118.00 FL
30	1		*REAR DOOR CHROME MOULDING	Scratched	275.00 FL	*165.00 FL
31	1		*REAR DOOR POWER WINDOW MOTOR	Bent / Jammed	577.00 FL	*360.00 FL
32	1		*REAR DOOR WINDOW GLASS O/S	Cut	325.90 FL	*325.90 FL
33	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Torn	798.30 FL	*605.00 FL
34	1		*REAR DOOR INNER LOCK O/S	Jammed	375.00 FL	*241.50 FL
35	1		*QUARTER WINOW	Not Necessary	283.90 FL	*- FL
36	1		*SET FRONT RH RIM	Repair	2,400.00 FS	*- FS
37	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
38	1		*SET FRONT DOOR CLIPS	Not Necessary	80.00 FS	*- FS
39	1		*SET REAR DOOR CLIPS	Not Necessary	80.00 FS	*- FS
40	2		*SOLAR FILM	Not Necessary	400.00 FS	*- FS
41	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,440.50	11,951.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,428.05	1,192.18
Total Parts (\$\$)	25,012.45	10,759.62

Report was unsubmitted during this print-out.

10/13/22, 1:51 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	380.00	30.00
2	REMOVE AND REFIT UNDERCARRIAGE AND STEERING RACK	New	1,000.00	300.00
3	REMOVE AND REFIT FRONT LINING ,TRIM AND GARNISH	New	150.00	0.00
4	REMOVE AND REFIT FRONT RH AND REAR RH DOOR	New	800.00	120.00
5	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,800.00	800.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	2,200.00	1,200.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	90.00
Gross Labour Cost (\$)			6,480.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >