



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2548M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LH MUDGUARD	TO REPAIR SEE LABOUR	850.00	-
1	REAR LH STEP BRACKET	TO REPAIR SEE LABOUR	350.00	-
	LESS 10% DISCOUNT		-120.00	-
			1,080.00	-
	<u>LABOUR</u>			
	TO REMOVE AND REPAIR REAR LH SIDE MEMBER INCLUDING PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR LH MUDGUARD AND REAR LH STEP BRACKET.		1,000.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR DAMAGED PORTION INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		300.00	180.00
	TO APPLY RUSTPROOFING, RESEAL TUFF-COATING TREATMENT TO REAR REPLACED / REPAIRED PARTS AND PANELS.	NOT NECESSARY	100.00	-
			1,400.00	380.00
GRAND TOTAL			2,480.00	380.00
RECOMMENDED COST OF REPAIRS				380.00

Report Ref No. CS3/SMO22004846/Kvy3e2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.