

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009083/UVY3Q2**Date:** 06/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00026002201

**Claimant Vehicle No :** SMN8009X **Insured Vehicle No :** SMH9200J

Date of Loss: 13/09/2022 Nature of Claim: TP Claim No: SNM22D206565/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN8009X**

Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ163912

Reg. Date: 29/08/2019 (Man. Year: 2019) Chassis No: JTEZB3GH70J004759

Colour: Purple Odometer: 79903 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,041.10	4,318.20	5,722.90	56.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	2,530.00	2,150.00	45.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,721.10</b>	<b>6,848.20</b>	<b>7,872.90</b>	<b>53.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,030.48</b>	<b>479.37</b>	<b>551.11</b>	<b>53.48</b>
<b>Nett Amount (S\$)</b>	<b>15,751.58</b>	<b>7,327.57</b>	<b>8,424.01</b>	<b>53.48</b>

INSPECTION

Date of Assignment: 15/09/2022

Date Inspected: 19/09/2022 Inspected At: Specialists Motor Pte Ltd (HQ)  
Blk 3018A Ubi Road 1, #01-24/25/26  
Singapore 408711

Estimated Period of Repair: 7.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2022)**Parts:** M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMN8009X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Distorted	904.00 FL	*904.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*REAR BUMPER SENSOR	N/S Shorted	1,445.70 FL	*481.90 FL
4	1		*REAR BUMPER SENSOR WIRING HARNESS	Serviceable	284.40 FL	*- FL
5	1		*REAR BUMPER SPONGE	Torn	122.60 FL	*122.60 FL
6	1		*REAR BUMPER LOWER LIP	Distorted	466.00 FL	*466.00 FL
7	1		*REAR BUMPER LOWER LIP REFLECTOR L&RH	N/S Broken	130.00 FL	*65.00 FL
8	1		*REAR BUMPER SIDE RETAINER L&RH	N/S Bent	211.60 FL	*105.80 FL
9	1		*REAR BOOT COVER	Badly Dented	2,126.40 FL	*2,126.40 FL
10	1		*REAR BOOT COVER LOCK	Not Necessary	631.90 FL	*- FL
11	1		*REAR BOOT COVER LATCH	Not Necessary	105.60 FL	*- FL
12	1		*REAR BOOT COVER EMBLEM (HARRIER)	Necessary	73.70 FL	*73.70 FL
13	1		*REAR BOOT COVER EMBLEM (TURBO)	Necessary	85.60 FL	*85.60 FL
14	2		*REAR BOOT COVER LAMP L&RH	Not Necessary	1,217.20 FL	*- FL
15	2		*REAR BOOT COVER DAMPER L&RH	Not Necessary	792.60 FL	*- FL
16	1		*REAR BOOT COVER W/STRIP	Serviceable	441.30 FL	*- FL
17	1		*REAR WINDSCREEN GLASS	Not Necessary	1,317.60 FL	*- FL
18	1		*REAR WINDSCREEN MOULDING	Necessary	105.60 FL	*105.60 FL
19	1		*REAR BOOT COVER REFLECTOR CENTRE	Not Necessary	1,055.20 FL	*- FL
20	1		*REAR BOOT COVER OPENING SENSOR	Not Necessary	86.30 FL	*- FL
21	1		*REAR END PANEL	Badly Dented	1,006.40 FL	*1,006.40 FL
22	1		*REAR END PANEL INNER GARNISH	Not Necessary	380.50 FL	*- FL
23	1		*SET REAR END PANEL INNER GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
24	1		*REAR NUMBER PLATE WIHT HOLDER	Not Necessary	50.00 FS	*- FS
25	1		*REAR END PANE SEALER	Necessary	80.00 FS	*50.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
27	1		*REAR BUMPER SENSOR	Necessary	15.00 FL	*15.00 FL
28	1		*REAR BUMPER SENSOR COVER	Necessary	29.60 FL	*29.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,324.80</b>	<b>5,727.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	3,283.70	1,409.40
<b>Total Parts (\$)</b>	<b>10,041.10</b>	<b>4,318.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT ,RENEW KNOCKING & WELDING REAR BOOT COVER ,REAR BUMPER ,REAR FENDER L&RH,REAR END PANEL ,REAR FLOOR PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	2,200.00	1,000.00
2	TUFF-KOTE ON DAMAGE PARTS	New	120.00	60.00
3	REMOVE & REFIX REAR BOOT INTERIOR UPHOLSTERY & ETC	New	380.00	80.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,680.00	1,200.00
5	REMOVE & REFIX REAR BUMPER SENSOR	New	120.00	50.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	40.00	20.00
7	REMOVE & REINSTALL REAR WINDSCREEN GLASS	New	140.00	120.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >