



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8485J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,590.00	1,590.00
1	FRONT BUMPER RH SIDE RETAINER	DISTORTED	48.00	48.00
1	HEADLAMP RH	CRACKED / CUT	4,580.00	4,390.00
1	HEADLAMP RH WIPER NOZZLE	SERVICEABLE	145.00	-
1	FRONT RH FENDER	BUCKLED	850.00	850.00
	LESS 10% DISCOUNT		-721.30	-687.80
			6,491.70	6,190.20
	<u>LABOUR</u>			
	REMOVE AND REFIT FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER. TO KNOCK, REPAIR FRT BUMPER AND REALIGN THE SAME.		500.00	400.00
	PUTTY AND RESPRAY FRT BUMPER, FRT RH FENDER.		500.00	440.00
	TO REPROGRAMME HEADLAMP SYSTEM.		150.00	120.00
			1,150.00	960.00
	GRAND TOTAL		7,641.70	7,150.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,700.00

Report Ref No. CS/AWA22009084/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.