

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22009087/EVY3Q2**Date:** 17/10/2022**REFERENCE**

Insured/Claimant:	FOO FANG CHEE	Policy No:	SP2001439724		
Date of Loss:	10/09/2022	Nature of Claim:	OD	Claim No:	202222006702SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN3879U		
Make & Model:	HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A)	Engine No:	G4FC9U595891
Reg. Date:	13/02/2009 (Man. Year: 2009)	Chassis No:	KMHDU41BR9U688304
Colour:	Black	Odometer:	166316 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$13,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Cinturato 5 mm	Rear Left Side:	Cinturato 5 mm
Front Right Side:	Cinturato 5 mm	Rear Right Side:	Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,645.50	7,283.20	1,362.30	15.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	2,510.00	220.00	8.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,375.50	9,793.20	1,582.30	13.91
Approved Total (Overridden) (S\$)		7,850.00		
- Excess (S\$)	0.00	3,100.00	-3,100.00	
(S\$)	11,375.50	4,750.00	6,625.50	58.24
+ GST 7.00/7.00% (S\$)	796.29	332.50	463.79	58.24
Nett Amount (S\$)	12,171.79	5,082.50	7,089.29	58.24

INSPECTION

Date of Assignment:	15/09/2022 Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	16/09/2022 Inspected At:	15 FAN YONG ROAD SINGAPORE 629792
Estimated Period of Repair:	7.0 days	Repairer:Mova Automotive Pte Ltd (Bukit Merah)

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2022)

Parts: 143 HYUNDAI AVANTE 1.6 HD DOHC ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN3879U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	520.00 F	*520.00 F
2	1		*FRONT BONNET OUTER RUBBER (WCP)	Torn	95.00 F	*95.00 F
3	1		*FRONT BONNET INSULATOR (WCP)	Crushed	210.00 F	*210.00 F
4	1		*FRONT BONNET INSULATOR CLIPS	Necessary	40.00 FS	*20.00 FS
5	1		*FRONT BONNET HINGE LH (WCP)	Bent	48.00 F	*48.00 F
6	1		*FRONT BONNET HINGE RH (WCP)	Bent	48.00 F	*48.00 F
7	1		*FRONT BONNET LOCK (WCP)	Bent	55.00 F	*55.00 F
8	1		*FRONT BONNET CABLE (WCP)	Cut	40.00 F	*40.00 F
9	1		*FRONT BONNET LOCK STAY PANEL (WCP)	Broken	75.00 F	*75.00 F
10	1		*FRONT SUPPORT PANEL (WCP)	Broken	460.00 F	*460.00 F
11	1		*FRONT AIR CLEANER DUCT (WCP)	Broken	196.00 F	*196.00 F
12	1		*FRONT AIR CLEANER HOSE (WCP)	Broken	110.00 F	*110.00 F
13	1		*FRONT GRILLE (WCP)	Broken	180.00 F	*180.00 F
14	1		*FRONT GRILLE EMBLEM (WCP)	Broken	48.00 F	*48.00 F
15	1		*FRONT GRILLE MOULDING (WCP)	Broken	110.00 F	*110.00 F
16	1		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
17	1		*FRONT BUMPER (WCP)	Broken	380.00 F	*380.00 F
18	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	150.00 F	*150.00 F
19	1		*FRONT BUMPER INNER SPONGE (WCP)	Broken	95.00 F	*95.00 F
20	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Broken	30.00 F	*30.00 F
21	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Broken	30.00 F	*30.00 F
22	1		*FRONT BUMPER LOWER GRILLE (WCP)	Broken	62.00 F	*62.00 F
23	1		*FRONT BUMPER FINISHER COVER RH (WCP)	Crushed	46.00 F	*46.00 F
24	1		*HEADLAMP LH (WCP)	Broken	420.00 F	*420.00 F
25	1		*HEADLAMP RH (WCP)	Broken	420.00 F	*420.00 F
26	1		*HORN (WCP)	Bent	72.00 F	*72.00 F
27	1		*WIPER TANK (WCP)	Broken	80.00 F	*80.00 F
28	1		*SPARE TANK (WCP)	Crushed	62.00 F	*62.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*RADIATOR (WCP)	Bent	580.00 F	*580.00 F
30	1		*RADIATOR FAN ASSY (WCP)	Broken	560.00 F	*560.00 F
31	1		*RADIATOR FAN GUARD (WCP)	Broken	210.00 F	*210.00 F
32	1		*RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
33	1		*AIR COND CONDENSOR (WCP)	Bent	620.00 F	*620.00 F
34	1		*AIR COND LIQUID TUBE (WCP)	Not Necessary	175.00 F	*- F
35	1		*AIR COND PRESSURE PIPE (WCP)	Not Necessary	380.00 F	*- F
36	1		*AIR COND COOLNIG PIPE (WCP)	Not Necessary	158.00 F	*- F
37	1		*INKLET MANIFOLD (WCP)	Not Necessary	480.00 F	*- F
38	1		*FRONT FENDER LH (WCP)	Bent	250.00 F	*250.00 F
39	1		*FRONT FENDER RH (WCP)	Bent	250.00 F	*250.00 F
40	1		*FRONT NUMBER PLATE	Broken	30.00 FS	*30.00 FS
41	1		*FRONT NUMBER PLATE HOLDER	Broken	20.00 FS	*20.00 FS
42	1		*FRONT WHEEL HOUSE LH/RH (REPAIR) (NPA) (WCP)	Repair	-	*- F
43	1		*FRONT WHEEL HOUSE CHASIS LH/RH (REPAIR) (NPA)(WCP)	Repair	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$)	7,875.00	6,632.00
+ Margin on L,N Items 10.00/10.00% (\$)	770.50	651.20
Total Parts (\$)	8,645.50	7,283.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACE, REFIT RADIATOR, RADIATOR FAN ASSY, AIRCOND CONDENSER, AIR COND LIQUID TUBE, AIR COND PIPE & ETC.	New	120.00	80.00
2	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	30.00
3	TO HYDRAOLICALLY JACK & REALIGN FRONT BOTH CHASIS FRAME & ETC. BACK TO ORIGINAL OPERATIONS	New	280.00	250.00
4	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT WHEEL HOUSE L/R, FRONT WHEEL HOUSE CHASSIS L/R, FRONT FENDER L/R & ETC. BACK TO ORIGINAL CONDITIONS	New	850.00	850.00
5	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT GRILLE, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT WHEEL HOUSE L/R, FRONT FENDER L/R & ETC.	New	1,300.00	1,200.00
6	TO REFILL AIR COND GAS & VACUUM	New	100.00	100.00
Gross Labour Cost (\$\$)			2,730.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >