

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22009089/RNY3E2  
**Date:** 15/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000747613
<b>Claimant Vehicle No :</b>	SLT4442J	<b>Insured Vehicle No :</b>	SKQ1732U
Date of Loss:	13/09/2022	Nature of Claim:	TP
		Claim No:	202222006710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT4442J</b>	Engine No:	L15B4427760
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11227758
Reg. Date:	30/10/2017 (Man. Year: 2017)	Odometer:	84576 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,565.08	4,158.00	5,407.08	56.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,220.00	2,080.00	48.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,865.08</b>	<b>6,378.00</b>	<b>7,487.08</b>	<b>54.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
<b>(S\$)</b>	13,865.08	5,100.00	8,765.08	63.22
<b>+ GST 8.00/8.00% (S\$)</b>	1,109.21	408.00	701.21	63.22
<b>Nett Amount (S\$)</b>	<b>14,974.29</b>	<b>5,508.00</b>	<b>9,466.29</b>	<b>63.22</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	15/09/2022		
Date Inspected:	15/09/2022	Inspected At:	H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	7.0 days		

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLT4442J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,450.00 FL	*1,100.00 FL
2	1		*TAIL GATE WEATHER STRIP	Necessary	185.00 FL	*135.20 FL
3	1		*TAIL GATE INNER LOCK	Not Necessary	310.00 FL	*- FL
4	1		*TAIL GATE INNER TRIM	Cracked	325.00 FL	*289.00 FL
5	1		*TAIL GATE HONDA LOGO	Not Necessary	53.00 FL	*- FL
6	1		*TAIL GATE VEZEL EMBLEM	Necessary	55.00 FL	*55.00 FL
7	1		*TAIL GATE I-VTEC EMBLEM	Necessary	58.00 FL	*58.00 FL
8	1		*N/S TAIL GATE REFLECTOR	Not Necessary	350.00 FL	*- FL
9	1		*N/S TAIL LAMP	Not Necessary	650.00 FL	*- FL
10	1		*REAR BUMPER FASCIA	Deformed	1,120.00 FL	*880.00 FL
11	1		*N/S REAR BUMPER SIDE COVER	Deformed	470.00 FL	*195.00 FL
12	1		*N/S REAR BUMPER BRACKET	Not Necessary	70.00 FL	*- FL
13	1		*N/S REAR BUMPER SIDE RETAINER	Not Necessary	64.00 FL	*- FL
14	1		*N/S REAR BUMPER REFLECTOR	Scratched	144.00 FL	*144.00 FL
15	1		*REAR BUMPER CENTER COVER (ACCESSORIES)	Scratched	850.00 FL	*650.00 FL
16	1		*REAR BUMPER LOWER GARNISH	Deformed	422.60 FL	*266.50 FL
17	1		*N/S REAR FENDER	Repair	1,080.00 FL	*- FL
18	1		*N/S REAR FENDER INNER GARNISH	Cracked	320.00 FL	*320.00 FL
19	1		*N/S RERA FENDER WHEEL ARCH GARNISH	Cracked	150.00 FL	*150.00 FL
20	1		*REAR END PANEL	Repair	620.00 FL	*- FL
21	1		*REAR END PANEL INNER GARNISH	Cracked	216.00 FL	*122.30 FL
22	1		*REAR WINDSCREEN GLASS MOLDING	Necessary	150.00 FL	*120.00 FL
23	1		*REAR FLOOR PANEL	Repair	1,275.00 FS	*- FS
24	1		*TOOLS BOX	Cracked	250.00 FS	*250.00 FS
25	1		*REAR SPARE TYRE BOARD	Not Necessary	280.00 FS	*- FS
26	1		*SET REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
27	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*60.00 FS
28	1		*REAR WINDSCREEN INNER GUM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,387.60</b>	<b>5,055.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,822.52	897.00
<b>Total Parts (\$\$)</b>	<b>9,565.08</b>	<b>4,158.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES	New	1,800.00	900.00
2	TO PUTTY AND SPRAY PAINTING	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	120.00	0.00
4	TO TRANSFER TAIL GATE	New	120.00	60.00
5	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
6	TO RE-SEAL ANTI RUST	New	150.00	40.00
7	REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	220.00	120.00
9	REMOVE AND REFIX CUSHION SEAT, GARNISH, CARPET & ETC	New	250.00	60.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,300.00</b>
				<b>2,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >