

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009093/EQY3Q2**Date:** 31/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00079712205	
<b>Claimant Vehicle No :</b>	SMX6055Y	<b>Insured Vehicle No :</b>	GBG2960E	
Date of Loss:	06/09/2022	Nature of Claim:	TP	Claim No: SNM22D206382/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMX6055Y</b>		Engine No:	32676231B38A15A
Make & Model:	BMW X1 SDRIVE18I, 1.5 X LINE LED HL (A)		Chassis No:	WBA32AA0605S53433
Reg. Date:	21/01/2021 (Man. Year: 2020)		Odometer:	27368 km
Colour:	Blue			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,612.54	3,654.29	2,958.25	44.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,190.00	5,665.00	2,525.00	30.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>14,802.54</b>	<b>9,319.29</b>	<b>5,483.25</b>	<b>37.04</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,036.18	652.35	383.83	37.04
<b>Nett Amount (\$\$)</b>	<b>15,838.72</b>	<b>9,971.64</b>	<b>5,867.08</b>	<b>37.04</b>

**INSPECTION**

Date of Assignment:	15/09/2022	Performance Motors Limited (Alexandra)
Date Inspected:	21/09/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 31 Oct 2022)

**Parts:** M1-SUV      BMW X1 SDRIVE18I 1.5 X LINE LED HL (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMX6055Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	3		*RUBBER MOUNTING	Not Necessary	54.45 FS	*- FS
3	1		*TAILPIPE TRIM BRIGHT CHROME	Not Necessary	125.55 FS	*- FS
4	1		*REAR SILENCER	Not Necessary	1,108.15 FS	*- FS
5	1		*BOOTLID	Dented	1,298.95 FS	*1,298.95 FS
6	1		*REAR BUMPER TRIM PANEL (X LINE)	Cut	226.95 FS	*226.95 FS
7	1		*RR BUMPER CARRIER	Not Necessary	523.75 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED	Not Necessary	907.80 FS	*- FS
9	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Cut	266.90 FS	*266.90 FS
10	10		*PLUG IN NUT	Not Necessary	31.00 FS	*- FS
11	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	37.70 FS	*- FS
12	1		*REAR WINDOW (ESG)	No	815.55 FS	*815.55 FS
13	1		*BOOTLID SEALING	Not Necessary	169.85 FS	*- FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
15	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
16	6		*BLIND RIVET NUT M6	No	16.20 FS	*16.20 FS
17	1		*3M SF PREMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS
18	3		*EXPANDING NUT	Necessary	3.00 FS	*3.00 FS
19	1		*EXPANDING NUT	Necessary	1.00 FS	*1.00 FS
20	2		*EMBLEM GROMMET	Necessary	1.90 FS	*1.90 FS
21	1		*LETTERING S DRIVE 18I	Necessary	98.35 FS	*98.35 FS
22	1		*LETTERINGG X1	Necessary	65.60 FS	*65.60 FS
23	12		*BUMP STOP	Necessary	39.60 FS	*39.60 FS
24	20		*EXPANDING RIVET BLACK	Necessary	28.00 FS	*28.00 FS
25	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
26	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	72.85 FS	*72.85 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **6,612.54**      **3,654.29**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE TAILGATE ,REAR BUMPER CARRIER AND REAR BUMPER	New	3,400.00	2,125.00
2	TO RESPRAY TAILGATE AND REAR BUMPER	New	2,076.00	1,972.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECK FOR LEAK	New	531.00	0.00
4	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK ELECTRICAL	New	177.00	168.00
6	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	545.00
7	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO CONDUCT WATER LEAK TESTS	New	75.00	71.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
10	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,190.00</b>	<b>5,665.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >