



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 6505B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH FRONT DOOR	DENTED	1,055.60	1,055.60
1	RH REAR DOOR	DENTED	1,011.50	1,011.50
1	RH REAR DOOR INNER TRIM BOARD	NOT NECESSARY	478.60	-
1	SET RH REAR DOOR INNER TRIM BOARD CLIPS	NOT NECESSARY	30.00	-
1	SET RH REAR DOOR BLACK TAPE	NECESSARY	199.50	199.50
1	RH REAR GLASS REGULATOR	NOT NECESSARY	343.20	-
1	RH REAR DOOR REGULATOR MOTOR	NOT NECESSARY	355.30	-
1	RH REAR DOOR ACTUATOR	NOT NECESSARY	387.50	-
1	RH REAR DOOR OUTER MOULDING	NOT NECESSARY	199.90	-
1	RH REAR DOOR W/STRIP	NOT NECESSARY	198.50	-
1	RH REAR FENDER (NPA)	NOT NECESSARY	-	-
1	RH ROCKER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER	NOT NECESSARY	789.60	-
1	RH REAR BUMPER RETAINER	NOT NECESSARY	88.50	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	30.00	-
1	RH REAR MUDFLAP	NOT NECESSARY	166.50	-
1	RH TAIL LAMP	NOT NECESSARY	798.60	-
	LESS 15% DISCOUNT		-919.92	-339.99
			5,212.88	1,926.61
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RH REAR RIM (SN)	NOT NECESSARY	550.00	-
1	SUNDRIES (SN)	NECESSARY	80.00	30.00
			630.00	30.00
<b><u>LABOUR</u></b>				
	LABOUR FOR FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF RH ROCKER PANEL.		1,000.00	400.00
	TO RESPRAY RH REAR FENDER.	NOT NECESSARY	300.00	-
	TO RESPRAY REAR BUMPER.	NOT NECESSARY	300.00	-
	TO RESPRAY RH ROCKER PANEL.		300.00	200.00
	TO RESPRAY RH FRONT DOOR.		300.00	200.00

Report Ref No. CS/SMR22009097/Eqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY RH REAR DOOR.		300.00	200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		50.00	30.00
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.		150.00	50.00
	TO REMOVE AND REFIT BOTH DOOR COMPONENT.		300.00	100.00
	WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO ROTATE AND BALANCE RH REAR RIM.	NOT NECESSARY	80.00	-
	RUST PROOFING.		100.00	30.00
			3,280.00	1,210.00
<b>GRAND TOTAL</b>			<b>9,122.88</b>	<b>3,166.61</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,000.00</b>
---	--	--	-----------------

Report Ref No. CS/SMR22009097/Eqy3m4

**CHEN TSUE YEE**

**Automotive Assessor**

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.