

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009104/RWY3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00005872101
Claimant Vehicle No :	SMZ1363E	Insured Vehicle No :	SMM6238U
Date of Loss:	22/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205155/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ1363E	Engine No:	2ZR2G89853
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU303091844
Reg. Date:	12/04/2021 (Man. Year: 2020)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,337.28	1,486.54	5,850.74	79.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	640.00	2,290.00	78.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,267.28	2,126.54	8,140.74	79.29
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	10,267.28	1,700.00	8,567.28	83.44
+ GST 7.00/7.00% (S\$)	718.71	119.00	599.71	83.44
Nett Amount (S\$)	10,985.99	1,819.00	9,166.99	83.44

INSPECTION

Date of Assignment:	15/09/2022	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	15/09/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMZ1363E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	1,598.00 FL	*- FL
2	1		*TAILGATE WEATHERSTRIP	Not Necessary	212.00 FL	*- FL
3	1		*TAILGATE OUTER GARNISH	Cut	521.00 FL	*521.00 FL
4	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	108.00 FL	*- FL
5	1		*TAILGATE EMBLEM PRIUST	Necessary	89.40 FL	*54.60 FL
6	1		*TAILGATE LOGO	Not Necessary	82.30 FL	*- FL
7	1		*TAILGATE EMBLEM HYBRID	Necessary	78.00 FL	*53.50 FL
8	1		*TAILGATE DETECTOR	Not Necessary	321.00 FL	*- FL
9	1		*TAILGATE LOCK	Not Necessary	312.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	658.00 FL	*658.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	224.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Not Necessary	350.50 FL	*- FL
13	2		*REAR BUMPER BRACKET	Not Necessary	228.00 FL	*- FL
14	1		*REAR BUMPER LIP	Deformed	728.90 FL	*654.96 FL
15	1		*REAR BUMPER REFLECTOR RH	Not Necessary	68.00 FL	*- FL
16	1		*REAR BUMPER TOP REFLECTOR RH	Not Necessary	312.00 FL	*- FL
17	1		*REAR BUMPER UNDER COVER LH	Not Necessary	321.00 FL	*- FL
18	1		*REAR BUMPER UNDER COVER RH	Not Necessary	251.00 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	712.00 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	287.00 FL	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	398.00 FL	*- FL
22	2		*REAR FLOOR PANEL TOP SIDE SPONGE	Not Necessary	624.00 FL	*- FL
23	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
25	1		*REAR REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
26	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,034.10	1,972.06
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,696.82	485.52
Total Parts (\$\$)	7,337.28	1,486.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	150.00	0.00
2	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	40.00
3	TO REMOVE AND REFIT REAR GLASS	New	150.00	0.00
4	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY	New	200.00	0.00
5	REMOVE AND RENEW TAILGATE MECHANISM	New	80.00	0.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	300.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	300.00
Gross Labour Cost (S\$)			2,930.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >