1/19/23, 3:19 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22009113/UPA3Q2

4P10D42206

19/01/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100367628 **Claimant Vehicle GBJ2663Y** Insured Vehicle No: SKM5576Z

No:

Date of Loss: 06/06/2022 Nature of Claim: TP Claim No: 3161282122SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBJ2663Y** 

MITSUBISHI CANTER, 3.0 D FEA01BR2SDEK Make & Model: Engine No:

(CBU) (M) Reg. Date: 04/03/2019 (Man. Year: 2018) FEA01BA30065 Chassis No: Colour: Orange Odometer: 100014 km

**Engine Capacity:** 2998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

CONDITION OF TYRES

195 R15 Front Tyre Size: Rear Tyre Size: 195 R15 (D) Austone 6/6 mm Front Left Side: Austone 6 mm Rear Left Side: Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,848.40	3,039.00	1,809.40	37.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	620.00	210.00	25.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total	(S\$) 5,678.40	3,659.00	2,019.40	35.56
Approved Total (Overridden)	(S\$)	2,900.00		
Nett Amount	(S\$) 5,678.40	2,900.00	2,778.40	48.93
+ Loss of Use	(3.0 x S\$80.00/day) (S\$)	240.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	3,142.00		

**INSPECTION** 

Date of Assignment: 16/09/2022

Liu's Brother Auto Engineering Workshop (kaki

Bukit) (HQ)

Date Inspected: 16/09/2022 Inspected At: Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt

Singapore 417883, Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAIL LAMP	Serviceable	496.40 F	*- FL
2	1		*REAR EXHAUST BOX	Dented	3,752.00 F	*3,752.00 FL
3	1		*REAR EXHAUST BOX SENSOR	Damaged	600.00 F	*300.00 FL
F=Fra	ınchise	part. L=ListItem	Disc.	-		
				Sub Total (S\$)	4,848.40	4,052.00
			- List Item Discount or	L Items 0.00/25.00% (S\$)	0.00	1,013.00
				Total Parts (S\$)	4,848.40	3,039.00
			Report was unsubmitted	during this print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	20.00				
2	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	400.00				
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	200.00	200.00				
	Gross Labour Cost (S\$)		830.00	620.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >