

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009121/UWY3M4**Date:** 10/10/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001459644

Claimant Vehicle No : GBF7493J**Insured Vehicle No :** SMP1862J

Date of Loss: 07/09/2022

Nature of Claim: TP

Claim No: 287040

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF7493J**

Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR E5 W/RC (M)

Engine No: K9KC400D056097

Reg. Date: 27/02/2017 (Man. Year: 2016)

Chassis No: VSKYBAM20Z0136469

Colour: Silver

Odometer: 139603 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Austone 6 mm

Rear Left Side: Austone 6 mm

Front Right Side: Austone 6 mm

Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,790.60	2,191.87	3,598.73	62.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,340.00	620.00	31.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,750.60	3,531.87	4,218.73	54.43
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	7,750.60	2,800.00	4,950.60	63.87

INSPECTION

Date of Assignment: 07/10/2022

Date Inspected: 16/09/2022 Inspected At:

LIU'S BROTHER AUTO ENGINEERING

WORKSHOP

1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @

KAKI BUKIT

SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2022)	
Parts:	N/A	NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR E5 W/RC (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7493J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAILGATE	Dented/Bent	1,545.40 F	*1,102.20 FN
2	1		*REAR RH TAILGATE HINGE LOWER	Not Necessary	195.00 F	*- FN
3	1		*REAR RH TAILGATE LOCK UPPER	Not Necessary	90.50 F	*- FN
4	1		*REAR RH TAILGATE LOCK LOWER	Not Necessary	105.50 F	*- FN
5	1		*REAR RH TAILGATE WEATHERSTRIP	Not Necessary	82.60 F	*- FN
6	1		*REAR RH TAILGATE DCI EMBLEM	Necessary	70.70 F	*70.70 FN
7	1		*REAR RH TAILGATE 6 PAX STICKER	Necessary	15.00 FS	*10.00 FS
8	1		*REAR RH TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
9	1		*REAR RH TAIL LAMP	Cracked	319.70 F	*309.80 FN
10	1		*REAR RH BODY PANEL (FENDER)	Repair	1,891.60 F	*- FN
11	1		*REAR RH BUMPER RETAINER O/S	Bent	145.00 F	*66.80 FN
12	1		*REAR RH BUMPER REFLECTOR	Not Necessary	47.90 F	*- FN
13	1		*REAR BUMPER	Dented	624.80 F	*485.90 FN
14	1		*SET REAR BUMPER CLIPS	Necessary	78.00 FS	*30.00 FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
16	1		*REAR BUMPER SPONGE	Torn	88.90 F	*88.90 FN
17	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	5,790.60	2,404.30
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	212.43
Total Parts (\$)	5,790.60	2,191.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	100.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
3	REMOVE AND REFIX REAR TAILGATE COMPONENTS & MECHANISM	New	60.00	50.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	40.00
5	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	900.00	580.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	550.00
Gross Labour Cost (\$\$)			1,960.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >