

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22009123/AVY3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : GBF4638D**Insured Vehicle No :** SKS9083X

Date of Loss: 13/09/2022

Nature of Claim: TP

Claim No: 2022 22006754FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF4638D**

Make & Model: TOYOTA HIACE, 2.5 (A)

Engine No: 1KD2654765

Reg. Date: 16/11/2016 (Man. Year: 2016)

Chassis No: JTFHT02P500207284

Colour: White

Odometer: 196703 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,950.05	5,141.00	4,809.05	48.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,160.00	2,370.00	2,790.00	54.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,110.05	7,511.00	7,599.05	50.29
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	15,110.05	6,000.00	9,110.05	60.29
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 16/09/2022

Date Inspected: 16/09/2022 Inspected At:

Unimotor Company - Kaki Bukit (HQ)

1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)

Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jun 2023)	
Parts:	N/A	TOYOTA HIACE 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4638D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE ASSY	Dented	2,199.60 FL	*1,855.00 FL
2	2		*REAR TAILGATE ABSORBER	Not Necessary	520.60 FL	*- FL
3	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	78.60 FL	*78.60 FL
4	1		*REAR TAILGATE TOYOTA HIACE STICKER	Necessary	61.20 FL	*61.20 FL
5	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	186.60 FL	*- FL
6	1		*REAR TAILGATE LOCK	Damaged	313.60 FL	*313.60 FL
7	1		*REAR TAILGATE LOCK CONTROL	Not Necessary	479.90 FL	*- FL
8	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	93.10 FL	*- FL
9	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	444.10 FL	*- FL
10	1		*REAR TAILGATE WEATHERSTRIP	Cut	255.50 FL	*255.50 FL
11	1		*REAR R/H TAILLAMP ASSY	Cracked	379.60 FL	*379.60 FL
12	1		*REAR R/H TAILLAMP PANEL	Dented	384.60 FL	*384.60 FL
13	1		*REAR R/H TAILLAMP LOWER COVER	Deformed	88.30 FL	*88.30 FL
14	1		*REAR R/H TAILLAMP LOWER BRACKET	Not Necessary	41.30 FL	*- FL
15	1		*REAR BUMPER ASSY	Distorted	512.80 FL	*512.80 FL
16	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
17	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	64.80 FL	*32.40 FL
18	1		*REAR R/H AIR DUCT	Cracked	94.60 FL	*94.60 FL
19	1		*REAR END PANEL (OUTER)	Dented	995.60 FL	*583.00 FL
20	1		*REAR PANEL (INNER)	Repair	887.60 FL	*- FL
21	1		*REAR END PANEL TOP CHROME STRIP	Bent	123.80 FL	*123.80 FL
22	1		*R/H FENDER PANEL	Buckled	2,885.40 FL	*1,675.00 FL
23	1		*REAR WHEEL CARRIER ASSY	Not Necessary	366.40 FL	*- FL
24	1		*REAR WHEEL CARRIER LOCK ASSY	Not Necessary	74.20 FL	*- FL
25	1		*REAR EXHAUST PIPE ASSY	Not Necessary	1,055.60 FL	*- FL
26	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	56.00 FL	*- FL
27	1		*REAR WINDSCREEN GLASS DAM RUBBER	Necessary	60.00 FS	*60.00 FS
28	1		*R/H SIDE FENDER GLASS DAM RUBBER	Not Necessary	60.00 FS	*- FS
29	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
30	1		*REAR TAILGATE 7 PAX STICKER	Necessary	15.00 FS	*15.00 FS
31	1		*REAR SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
					Sub Total (\$\$)	13,123.40 6,758.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,173.35 1,617.00
					Total Parts (\$\$)	9,950.05 5,141.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE DAMAGED PORTION	New	200.00	30.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	2,600.00	1,200.00
3	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,300.00	1,000.00
4	TO DISM/REFIX REAR /R/H INNER ROOF TOP GARNISH	New	180.00	60.00
5	TO SPRAY UNDERCOATING IN REPAIR	New	400.00	80.00
6	TO DISM/RENEW REAR EXHAUST PIPE	New	200.00	0.00
7	TO DISM/REFIX REPAIR /R/H FENDER WINDSCREEN GLASS	New	280.00	0.00
Gross Labour Cost (\$\$)			5,160.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >