



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

T P Aulianz.

LKK

JTHH 02P500

VENN

DATE: 09/09/2021 OUR REF: UAPL1484
REPAIR ESTIMATE YOUR TOYOTA HIACE NO. ~~GBK4288~~ ~~GBF4638D~~

- 1 REAR TAILGATE ASSY *Dented*
- 2 REAR TAILGATE ABSORBER *New*
- 1 REAR TAILGATE TOYOTA EMBLEM *3 New*
- 1 REAR TAILGATE TOYOTA HIACE STICKER *New*
- 1 REAR TAILGATE OUTER GARNISH *New*
- 1 REAR TAILGATE LOCK *Dented*
- 1 REAR TAILGATE LOCK CONTROL *New*
- 1 REAR TAILGATE LOCK STRIKER *New*
- 1 REAR TAILGATE INNER TRIM BOARD *New*
- 1 REAR TAILGATE WEATHERSTRIP *ht*
- 1 REAR R/H TAILLAMP ASSY *Cracked*
- 1 REAR R/H TAILLAMP PANEL *Dented*
- 1 REAR R/H TAILLAMP LOWER COVER *New*
- 1 REAR R/H TAILLAMP LOWER BRACKET *New*
- 1 REAR BUMPER ASSY *Dented*
- 10 REAR BUMPER CLIP *New*
- 2 REAR BUMPER SIDE RETAINER *RH New*
- 1 REAR R/H AIR DUCT *Cracked*
- 1 REAR END PANEL (OUTER) *Dented*
- 1 REAR PANEL (INNER) *New*
- 1 REAR END PANEL TOP CHROME STRIP *But*
- 1 R/H FENDER PANEL *Breake*
- 1 REAR WHEEL CARRIER ASSY *New*
- 1 REAR WHEEL CARRIER LOCK ASSY *New*
- 1 REAR EXHAUST PIPE ASSY
- 2 REAR EXHAUST PIPE MOUNTING

\$	2,199.60	1855
\$	520.60	X
\$	78.60	✓
\$	61.20	✓
\$	186.60	X
\$	313.60	✓
\$	479.90	X
\$	93.10	X
\$	444.10	X
\$	255.50	✓
\$	379.60	✓
\$	384.60	✓
\$	88.30	✓
\$	41.30	✓
\$	512.80	✓
\$	50.00	30
\$	64.80	32.40
\$	94.60	✓
\$	995.60	+583
\$	887.60	✓
\$	123.80	✓
\$	2,885.40	1675
\$	366.40	X
\$	74.20	X
\$	1,055.60	X
\$	56.00	X
\$	12,693.40	
\$	3,173.35	
\$	9,520.05	

LESS 25%.....

SPECIAL NETT:-

- 1 REAR WINDSCREEN GLASS DAM RUBBER *New*
- 1 R/H SIDE FENDER GLASS DAM RUBBER *New*
- 1 REAR TAILGATE 70KM/H STICKER *3 New*
- 1 REAR TAILGATE 7 PAX STICKER *Dented*
- 1 REAR SET REVERSE SENSER

\$	60.00	✓
\$	60.00	X
\$	15.00	✓
\$	15.00	✓
\$	280.00	200

LABOUR CHANGE:-

- TO DISM/REWIRE DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO DISM/REFIX REAR/R/H INNER ROOF TOP GARNISH
- TO SPARY UNDERCOATING IN REPAIR
- TO DISM/RENEW REAR EXHAUST PIPE
- TO DISM/REFIX REAR/R/H FENDER WINDSCREEN GLASS

\$	200.00	30
\$	2,800.00	1200
\$	1,300.00	1000
\$	180.00	60
\$	400.00	80
\$	200.00	X
\$	280.00	X
\$	15,110.05	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6K

Total: 7511

H/S: 6K

09 Dyp