



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 33U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	CENTRE REAR TRELLIS	DENTED	502.65	502.65
1	REAR BUMPER CROSSMEMBER	REFIT	8,900.00	-
			9,402.65	502.65
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER DIFFUSER (MISHA) (SN)	CRACKED	31,400.00	25,600.00
1	REAR NUMBER PLATE (SN)	CRACKED	180.00	80.00
			31,580.00	25,680.00
	<u>LABOUR</u>			
	RENEW DAMAGED PARTS, RE-ALIGN AFFECTED AREA.		1,000.00	500.00
	CHECK LIGHTINGS & WIRINGS.		50.00	30.00
			1,050.00	530.00
	GRAND TOTAL		42,032.65	26,712.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,350.00

Report Ref No. CS3/SMO22005349/Kny3e2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.