

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009131/GCY3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00067042200
Claimant Vehicle No :	SKA8044K	Insured Vehicle No :	YQ3919U
Date of Loss:	11/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206587/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8044K	Engine No:	L13Z11038962
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGE68509S238931
Reg. Date:	01/04/2011 (Man. Year: 2009)	Odometer:	151738 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,593.00	5,852.40	2,740.60	31.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,510.00	1,290.00	33.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,393.00	8,362.40	4,030.60	32.52
Approved Total (Overridden) (S\$)		6,650.00		
(S\$)	12,393.00	6,650.00	5,743.00	46.34
+ GST 8.00/8.00% (S\$)	991.44	532.00	459.44	46.34
Nett Amount (S\$)	13,384.44	7,182.00	6,202.44	46.34

INSPECTION

Date of Assignment:	15/09/2022		
Date Inspected:	16/09/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	8.0 days		

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8044K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	797.00 FL	*523.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Broken	112.00 FL	*112.00 FL
3	1		*FRONT FENDER N/S	Dented	676.00 FL	*430.00 FL
4	1		*FRONT FENDER INNER COWLING N/S	Torn	85.00 FL	*85.00 FL
5	1		*FRONT SHOCK ABSORBER N/S	Bent	389.00 FL	*389.00 FL
6	1		*FRONT LOWER ARM N/S	Bent	287.00 FL	*287.00 FL
7	1		*FRONT WHEEL KNUCKLE N/S	Bent	377.00 FL	*377.00 FL
8	1		*FRONT WHEEL KNUCKLE BEARING N/S	Necessary	290.00 FL	*187.00 FL
9	1		*FRONT ENDLINK N/S	Not Necessary	126.00 FL	*- FL
10	1		*FRONT DOOR N/S	Dented	904.00 FL	*781.00 FL
11	1		*FRONT DOOR INNER TRIM BOARD N/S	Broken	483.00 FL	*483.00 FL
12	2		*FRONT DOOR HINGE N/S	Bent	204.00 FL	*140.00 FL
13	1		*FRONT DOOR OUTER MOULDING N/S	Not Necessary	125.00 FL	*- FL
14	1		*FRONT DOOR CHECKER N/S	Bent	65.00 FL	*65.00 FL
15	1		*FRONT DOOR OUTER HANDLE N/S	Not Necessary	92.00 FL	*- FL
16	1		*FRONT DOOR LOCK N/S	Jammed	133.00 FL	*133.00 FL
17	1		*FRONT DOOR WINDOW REGULATOR N/S	Bent	336.00 FL	*336.00 FL
18	1		*FRONT DOOR WINDOW MOTOR N/S	Jammed	186.00 FL	*186.00 FL
19	1		*FRONT DOOR WINDOW OUTER CHANNEL N/S	Bent	113.00 FL	*113.00 FL
20	1		*REAR DOOR N/S	Dented	815.00 FL	*750.00 FL
21	2		*REAR DOOR HINGE N/S	Not Necessary	204.00 FL	*- FL
22	1		*REAR DOOR OUTER MOULDING N/S	Not Necessary	125.00 FL	*- FL
23	1		*REAR DOOR CHECKET N/S	Not Necessary	65.00 FL	*- FL
24	1		*REAR DOOR WINDOW OUTER CHANNEL N/S	Not Necessary	89.00 FL	*- FL
25	1		*REAR FENDER N/S	Not Necessary	773.00 FL	*- FL
26	1		*HEADLAMP N/S	Cracked	987.00 FL	*744.00 FL
27	1		*WING MIRROR ASSY N/S	Broken	457.00 FL	*457.00 FL
28	10		*FRONT BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
29	1		*FRONT FENDER SEALANT N/S	Not Necessary	80.00 FS	*- FS
30	8		*FRONT FENDER INNER COWLING CLIPS N/S	Necessary	36.00 FS	*20.00 FS
31	8		*FRONT DOOR INNER TRIM BOARD CLIPS N/S	Necessary	36.00 FS	*20.00 FS
32	1		*REAR FENDER GLASS SEALANT N/S	Necessary	80.00 FS	*20.00 FS
33	1		*FRONT ALLOY WHEEL N/S	Cut	450.00 FS	*400.00 FS
34	1		*FRONT TYRE N/S	Not Necessary	280.00 FS	*- FS
35	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
36	1		*WING MIRROR QUARTER GARNISH N/S	Missing	125.00 FL	*125.00 FL
					Sub Total (\$\$)	10,477.00 7,193.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,884.00 1,340.60
					Total Parts (\$\$)	8,593.00 5,852.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,600.00	800.00
2	TO DISCONNECT N/S DOORS WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS OF POWER WINDOWS	New	100.00	0.00
3	TO REMOVE AND REFIT N/S FRONT & REAR DOOR COMPONENTS TO REPLACE N/S FRONT & REAR DOOR ,CHECK ALIGNMENT	New	200.00	120.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,400.00	1,200.00
5	TO REMOVE AND REFIT N/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	200.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	150.00	60.00
7	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	80.00
8	TO REMOVE AND REFIT N/S FRONT TYRE & RIM .TO PERFORM TYRE BALANCING	New	50.00	50.00
Gross Labour Cost (\$\$)			3,800.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >