



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 6476U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSY	GRAZED / DENTED	2,160.00	2,160.00
1	REAR BUMPER LEFT RETAINER	BENT / NECESSARY	89.00	89.00
1	REAR BUMPER RIGHT RETAINER	NOT NECESSARY	89.00	-
1	REAR BUMPER LEFT BRACKET	BENT / NECESSARY	83.00	83.00
1	REAR BUMPER RIGHT BRACKET	NOT NECESSARY	83.00	-
1	REAR BUMPER TOW COVER	NECESSARY	98.00	98.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	590.00	-
1	REAR LEFT AIR VENTILATOR	NOT NECESSARY	98.00	-
1	REAR LEFT TAILLAMP ASSY	CRACKED	853.00	853.00
1	REAR EXHAUST FULL COMPLETE SYSTEM ASSY	BENT / MALFUNCTION	3,800.00	3,200.00
1	SET REAR EXHAUST MUFFLER RUBBER MOUNTING	NOT NECESSARY	108.00	-
	LESS 5% DISCOUNT		-402.55	-324.15
			7,648.45	6,158.85
<u>SPECIAL NETT ITEMS</u>				
12	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	50.00
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER LEFT REVERSE SENSOR (SN)	MISSING	300.00	250.00
1	REAR BUMPER LOWER DIFFUSER (SN)	DENTED / GRAZED	1,200.00	915.00
10	REAR BUMPER LOWER DIFFUSER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER DIFFUSER SEALANT (SN)	NECESSARY	100.00	40.00
			1,820.00	1,285.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,200.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	30.00
	TO REMOVE AND INSTALL REAR EXHAUST FULL COMPLETE SYSTEM ASSY.		140.00	100.00

Report Ref No. CS3/ASM22001751/Tqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		180.00	60.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	30.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	40.00
	TO REPAIR, STRAIGHTEN AND ALIGN REAR LEFT FENDER ASSY.	NOT NECESSARY	180.00	-
	TOWING SERVICE.		100.00	80.00
			3,270.00	1,540.00
GRAND TOTAL			12,738.45	8,983.85
RECOMMENDED COST OF REPAIRS				8,983.85

Report Ref No. CS3/ASM22001751/Tqy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.