

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009135/ECE2**Date:** 30/12/2022**REFERENCE**

Insured/Claimant:	CHAN CHUI FUNN	Policy No:	1800031230-04	
Date of Loss:	14/09/2022	Nature of Claim:	OD	Claim No: 4329458399SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4854H		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK056464
Reg. Date:	28/03/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF43JA124722
Colour:	Blue	Odometer:	22471 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,499.00	10,149.84	12,349.16	54.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,402.00	4,052.00	6,350.00	61.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,901.00	14,201.84	18,699.16	56.83
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	32,351.00	13,651.84	18,699.16	57.80
+ GST 7.00/7.00% (S\$)	2,264.57	955.63	1,308.94	57.80
Nett Amount (S\$)	34,615.57	14,607.47	20,008.10	57.80

INSPECTION

Date of Assignment:	16/09/2022	
Date Inspected:	16/09/2022	Inspected At: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector Singapore 629857
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Deformed	254.00 FS	*203.20 FS
6	1		*RADIATOR AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,478.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Deformed	41.00 FS	*32.24 FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET	Broken	154.00 FS	*122.80 FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
17	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
18	1		*HORN BRACKET - LH	Not Necessary	33.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
20	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
22	1		*FRONT FENDER - LH	Dented	861.00 FS	*688.80 FS
23	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	81.00 FS	*64.24 FS
24	1		*FRONT FENDER BRACKET - LH	Bent	41.00 FS	*32.72 FS
25	7		*FRONT FENDER RIVET	Necessary	27.00 FS	*21.28 FS
26	1		*FRONT FENDER BRACE - LH	Bent	132.00 FS	*105.20 FS
27	1		*FRONT DEFORMATION ELEMENT BRACKET - LH	Not Necessary	55.00 FS	*- FS
28	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	260.00 FS	*208.00 FS
29	1		*FRONT WHEEL SPOILER	Deformed	82.00 FS	*65.12 FS
30	1		*FRONT SPOILER END PLATE - LH	Not Necessary	39.00 FS	*- FS
31	1		*FRONT FENDER OUTER LEDGE COVER - LH	Necessary	35.00 FS	*27.52 FS
32	1		*FRONT FENDER LEDGE COVER - LH	Necessary	26.00 FS	*20.16 FS
33	1		*HEADLIGHT - LH	Broken	8,294.00 FS	*6,635.20 FS
34	1		*HEADLIGHT POWER MODULE	Not Necessary	842.00 FS	*- FS
35	1		*HEADLIGHT CONTROL UNIT	Not Necessary	840.00 FS	*- FS
36	3		*COMPESATING PIECE	Not Necessary	137.00 FS	*- FS
37	1		*HEADLIGHT HOSE - LH	Not Necessary	42.00 FS	*- FS
38	1		*LIFT CYLINDER - LH	Not Necessary	231.00 FS	*- FS
39	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
40	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
41	1		*LOCK CARRIER	Not Necessary	1,478.00 FS	*- FS
42	1		*LOCK CARRIER SUPPORT - LH	Not Necessary	43.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - LH	Not Necessary	32.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE - LH	Deformed	14.00 FS	*10.88 FS
45	1		*RADIATOR AIR DUCT - UPPER	Not Necessary	19.00 FS	*- FS
46	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
47	6		*READY-MIX COOLANT	Not Necessary	297.00 FS	*- FS
48	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
49	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
50	1		*RADIATOR AIR GUIDE - RH	Broken	14.00 FS	*10.88 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	22,499.00
						10,149.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,200.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,500.00	1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			10,402.00	4,052.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >