

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009137/ENY3Q2**Date:** 30/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00046442200		
Claimant Vehicle No :	SLB4265Z	Insured Vehicle No :	SKA7814L		
Date of Loss:	13/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206586/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4265Z		Engine No:	L15Z12722055
Make & Model:	HONDA CITY, 1.5 (A)		Chassis No:	MRHGM6660GP000483
Reg. Date:	07/04/2016 (Man. Year: 2016)		Odometer:	139121 km
Colour:	Blue			
Engine Capacity:	1497 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,875.83	1,429.00	446.83	23.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,530.00	6,795.00	2,735.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,405.83	8,224.00	3,181.83	27.90
+ GST 7.00/7.00% (\$\$)	798.41	575.68	222.73	27.90
Nett Amount (\$\$)	12,204.24	8,799.68	3,404.56	27.90

INSPECTION

Date of Assignment:	15/09/2022		
Date Inspected:	03/10/2022	Inspected At:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	8.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2022)
Parts:	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4265Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID COMPTRUNK	Dented	396.30 FS	*396.30 FS
2	1		*LOCK ASSYTRUNK	Bent	80.10 FS	*80.10 FS
3	1		*STRIKERTRUNK LID	Not Necessary	8.55 FS	*- FS
4	1		*WEATHERSTRIPTRUNK LID	Crushed	63.82 FS	*63.82 FS
5	1		*EMBLEM H	Necessary	9.75 FS	*9.75 FS
6	1		*EMBLEMRR .CITY	Necessary	10.05 FS	*10.05 FS
7	1		*EMBLEMRR.I-VTEC	Necessary	10.50 FS	*10.50 FS
8	2		*CLIP TUBULAR	Necessary	3.60 FS	*3.60 FS
9	1		*TAILLIGHT ASSYR	Not Necessary	154.27 FS	*- FS
10	1		*TAILLIGHT ASSYR	Not Necessary	154.27 FS	*- FS
11	1		*LIGHT ASSY.R LID	Not Necessary	64.87 FS	*- FS
12	1		*LIGHT ASSYL LID	Not Necessary	64.87 FS	*- FS
13	1		*GARNISH ASSYRR LICENSE	Cut	55.27 FS	*55.27 FS
14	1		*FACERR BUMPER	Dented	347.77 FS	*347.77 FS
15	1		*SPACER R.RR.BUMPER SIDE	Broken	8.62 FS	*8.62 FS
16	1		*SPACERL.RR.BUMPER SIDE	Broken	8.62 FS	*8.62 FS
17	1		*CLIP BUMPER (4 PCS)	Necessary	6.90 FS	*6.90 FS
18	1		*PANEL COMPRR	Dented	288.75 FS	*288.75 FS
19	1		*LINING ASSYRR PANEL	Crushed	49.95 FS	*49.95 FS
20	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
21	1		*LID COMPSPARE TIRE	Crushed	39.00 FS	*39.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **1,875.83** **1,429.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	280.00	250.00
2	REMOVE & RENEW REVERSE SENSORS	New	280.00	250.00
3	STRAIGHTEN ALIGN TRUNK LID	New	650.00	325.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	650.00	580.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	650.00	580.00
6	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	3,900.00	3,250.00
7	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,120.00	1,560.00
Gross Labour Cost (\$\$)			9,530.00	6,795.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >