

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009139/UWY3M4**Date:** 10/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00170082202

Claimant Vehicle No : SDE7123J **Insured Vehicle No :** SJS5347Z

Date of Loss: 14/09/2022 Nature of Claim: TP Claim No: SNM22D206566/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDE7123J**

Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4532158

Reg. Date: 03/05/2017 (Man. Year: 2017) Chassis No: JHMRU1810GX202158

Colour: Silver Odometer: 130944 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,008.32	20.00	988.32	98.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,290.00	590.00	31.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,888.32	1,310.00	1,578.32	54.64
+ GST 7.00/7.00% (S\$)	202.18	91.70	110.48	54.64
Nett Amount (S\$)	3,090.50	1,401.70	1,688.80	54.64

INSPECTION

Date of Assignment: 16/09/2022

Date Inspected: 19/09/2022 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Oct 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDE7123J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE RR.BUMPER	Repair	832.70 FL	*- FL
2	8		*CLIP,BUMPER	Not Necessary	18.40 FL	*- FL
3	1		*4PCS ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
4	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	1,221.10 20.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	212.78 0.00
					Total Parts (\$\$)	1,008.32 20.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)	New	180.00	120.00
2	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON ATTACHMENT ITEMS	New	900.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	New	800.00	520.00
Gross Labour Cost (\$)			1,880.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >