

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009151/ENY3E2**Date:** 28/12/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00207062100

**Claimant Vehicle  
No :** SKE2111T**Insured Vehicle  
No :** SJY4427B

Date of Loss: 15/09/2022

Nature of Claim: TP

Claim  
No: SNM22D206607/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKE2111T**

Make &amp; Model: BMW I3, 647cc (A)

Engine No: HIDDEN

Reg. Date: 17/06/2022 (Man. Year: 2022)

Chassis No: WBY42DU080S426535

Colour: Black

Odometer: 10450 km

Engine Capacity: 0 cc

Market Value/New Car  
Price: N/ASum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R20	Rear Tyre Size:	275/40 R20
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,435.95	2,588.55	1,847.40	41.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	3,583.00	1,397.00	28.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,415.95</b>	<b>6,171.55</b>	<b>3,244.40</b>	<b>34.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	659.12	432.01	227.11	34.46
<b>Nett Amount (S\$)</b>	<b>10,075.07</b>	<b>6,603.56</b>	<b>3,471.51</b>	<b>34.46</b>

INSPECTION

Date of Assignment: 16/09/2022

Date Inspected: 10/11/2022 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
<b>Parts:</b>	143	BMW I3 647cc (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE2111T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	15		*EXPANDING RIVET	Necessary	25.50 FS	*21.00 FS
3	1		*REAR BUMPER PANEL PRIMED (PD)	Dented	1,593.30 FS	*1,593.30 FS
4	1		*REAR BUMPER BOTTOM TRIM PANE	Cut	297.75 FS	*297.75 FS
5	1		*REAR RH COVERING	Not Necessary	80.85 FS	*- FS
6	1		*REAR BUMPER CARRIER (BEV)	Not Necessary	776.85 FS	*- FS
7	1		*REAR RH BUMPER MOUNT	Not Necessary	118.75 FS	*- FS
8	1		*REAR BUMPER COVER PAINTED (F)	Cut	274.35 FS	*274.35 FS
9	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	48.80 FS	*- FS
10	1		*ADAPTER FOR SUPPORT REAR	Not Necessary	166.90 FS	*- FS
11	1		*RH BOTTOM COVER (I BLUE)	Cut	109.25 FS	*109.25 FS
12	1		*REAR RH BUMPER MOUNT	Not Necessary	209.70 FS	*- FS
13	2		*EMBLEM GROMMET	Necessary	1.90 FS	*1.90 FS
14	1		*PLAQUE	Necessary	72.85 FS	*72.85 FS
15	1		*UNDERBODY SH	Not Necessary	79.50 FS	*- FS
16	1		*UNDERBODY PANELLING REAR END	Not Necessary	102.20 FS	*- FS
17	1		*RH REFLECTOR (M)	Broken	39.80 FS	*39.80 FS
18	1		*DECOUPLING RING	Not Necessary	5.30 FS	*- FS
19	1		*ULTRASONIC SENSOR BLACK	Not Necessary	254.05 FS	*- FS
20	1		*LETTERING (I X3)	Necessary	98.35 FS	*98.35 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **4,435.95** **2,588.55**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND TO MAKE GOOD BOOT LID	New	2,550.00	1,275.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	2,076.00	1,972.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONN ETC TO NEW BUMPER INCLUDING RE CONNECT TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (S\$)</b>			<b>4,980.00</b>	<b>3,583.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >