

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009157/UWY3Q2**Date:** 06/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00119112101

**Claimant Vehicle No :** GBD3783J **Insured Vehicle No :** YQ4241J

Date of Loss: 14/09/2022 Nature of Claim: TP Claim No: SNM22D206584/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBD3783J**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) Engine No: 4P10B28649

Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: FEA01BA00436

Colour: White Odometer: 255859 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)

Front Left Side: Rovel 6 mm Rear Left Side: OHTSU 6/6 mm

Front Right Side: Rovel 6 mm Rear Right Side: OHTSU 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,458.00	2,207.25	6,250.75	73.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,330.00	1,920.00	59.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,708.00</b>	<b>3,537.25</b>	<b>8,170.75</b>	<b>69.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,708.00</b>	<b>2,800.00</b>	<b>8,908.00</b>	<b>76.08</b>

**INSPECTION**

Date of Assignment: 21/09/2022

Date Inspected: 21/09/2022 Inspected At: BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868

Estimated Period of Repair: 3.0 days Repairer: Profi Automotive

**Adjuster:** MARCUS CHUA**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Oct 2022)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD3783J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,671.00 FL	*1,671.00 FL
2	1		*REAR TAILGATE EMBLEM -MITSUBISHI	Necessary	251.00 FL	*185.00 FL
3	4		*REAR TAILGATE HINGE	Not Necessary	1,080.00 FL	*- FL
4	2		*REAR TAILGATE STOPPER	Not Necessary	152.00 FL	*- FL
5	2		*TAILGATE STOPPER BRACKET	Not Necessary	280.00 FL	*- FL
6	2		*REAR SIDE GATE LOCK	Not Necessary	452.00 FL	*- FL
7	2		*REAR SIDE GATE HINGE	Not Necessary	536.00 FL	*- FL
8	1		*REAR TAIL LAMP PANEL LH	Not Necessary	211.00 FL	*- FL
9	1		*REAR TAIL LAMP PANEL RH	Not Necessary	211.00 FL	*- FL
10	1		*REAR TAIL LAMP LH	Scratched	175.00 FL	*175.00 FL
11	1		*REAR TAIL LAMP RH	Not Necessary	175.00 FL	*- FL
12	1		*REAR FLOOR STEP BRACKET	Not Necessary	271.00 FL	*- FL
13	1		*REAR EXHAUST SILENCER	Not Necessary	850.00 FL	*- FL
14	2		*REAR EXHAUST MOUNTING	Not Necessary	120.00 FL	*- FL
15	1		*REAR NUMBER PLATE	Bent	100.00 FS	*14.00 FS
16	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
17	1		*12 PAX STICKER	Necessary	80.00 FS	*10.00 FS
18	1		*70KM/H STICKER	Necessary	80.00 FS	*10.00 FS
19	1		*REAR CANOPY	Not Necessary	1,800.00 FS	*- FS
20	1		*REAR TAILGATE INNER WOODEN BOARD	Cracked	850.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,745.00</b>	<b>2,715.00</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b>	1,287.00	507.75
<b>Total Parts (\$\$)</b>	<b>8,458.00</b>	<b>2,207.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	300.00	0.00
3	PANEL BEATING ON AFFECTED AREAS AND RENEW AFFECTED PARTS	New	1,200.00	680.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	600.00
5	APPLY ANTI -RUST ON AFFECTED AREAS	New	150.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,250.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >