

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009158/ANY3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00066102100		
Claimant Vehicle No :	GBK5582Y	Insured Vehicle No :	YL7978Z		
Date of Loss:	15/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206611/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5582Y	Engine No:	1KD2864625
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	KDY2318039987
Reg. Date:	03/09/2020 (Man. Year: 2019)	Odometer:	57354 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,491.47	9,546.80	5,944.67	38.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	2,100.00	1,710.00	44.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,301.47	11,646.80	7,654.67	39.66
Approved Total (Overridden) (\$\$)		9,300.00		
Nett Amount (\$\$)	19,301.47	9,300.00	10,001.47	51.82

INSPECTION

Date of Assignment:	22/09/2022	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	19/09/2022 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	8.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Dec 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5582Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cut	1,876.90 FL	*1,485.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	446.10 FL	*285.00 FL
3	1		*FRONT WINDSCREEN ERP STICKER	Not Necessary	20.00 FL	*- FL
4	1		*FRONT WIPER NOZZLE	Not Necessary	74.20 FL	*- FL
5	1		*FRONT WIPER MOTOR	Not Necessary	937.30 FL	*- FL
6	1		*FRONT WIPER LINKAGE	Bent	673.90 FL	*271.00 FL
7	1		*FRONT WIPER PANEL	Dented	692.50 FL	*692.50 FL
8	1		*FRONT CENTRE PANEL	Dented	2,053.00 FL	*1,642.00 FL
9	1		*FRONT CENTRE PANEL DYNA STICKER	Necessary	217.60 FL	*95.00 FL
10	1		*FRONT GRILLE	Cracked	944.50 FL	*582.00 FL
11	1		*FRONT GRILLE EMBLEM	Necessary	145.30 FL	*70.00 FL
12	2		*FRONT HEADLAMP	Cracked	2,332.20 FL	*2,332.20 FL
13	1		*C	Not Necessary	673.90 FL	*- FL
14	1		*FRONT LH SIDE MIRROR BRACKET	Bent	391.00 FL	*391.00 FL
15	1		*FRONT LH SIDE BIG MIRROR	Not Necessary	298.00 FL	*- FL
16	1		*FRONT LH SIDE SMALL MIRROR	Not Necessary	189.00 FL	*- FL
17	1		*FRONT DESKBOARD	Deformed	2,054.90 FL	*1,481.00 FL
18	1		*FRONT INNER PANEL	Repair	1,460.50 FL	*- FL
19	1		*AIRCOND BLOWER	Cracked	1,425.70 FL	*1,425.70 FL
20	1		*AIRCOND COIL	Cracked	3,266.20 FL	*1,950.00 FL
21	1		*AIRCOND FILTER DUCT	Not Necessary	209.30 FL	*- FL
22	1		*NOZZLE SCREW	Not Necessary	73.30 FL	*- FL
23	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
24	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,605.30	12,722.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,113.83	3,175.60
Total Parts (\$\$)	15,491.47	9,546.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY FRONT WINDSCREEN SEALANT	New	50.00	50.00
2	TO CHECK WIRING	New	80.00	30.00
3	REMOVE & REFIX FRONT WINDSCREEN	New	150.00	120.00
4	REMOVE & REFIX FRONT DASHBOARD	New	480.00	200.00
5	REMOVE & REINSTALL AIR CON FILL IN GAS	New	150.00	120.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	850.00
7	RESPRAY PAINTING	New	1,000.00	650.00
8	TUFF KOTE	New	100.00	80.00
Gross Labour Cost (S\$)			3,810.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >