



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3526R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	586.30	586.30
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	486.30	-
2	FRONT BUMPER SIDE RETAINER @\$75.40	DAMAGED	150.80	38.00
1	FRONT BUMPER FOG LAMP	CRACKED	254.10	254.10
1	FRONT BUMPER FOG LAMP OUTER GARNISH	NOT NECESSARY	85.40	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	980.30	-
1	FRONT HEADLAMP	CUT	781.20	781.20
1	FRONT FENDER	NOT NECESSARY	650.10	-
1	FRONT FENDER EMBLEM VVTI	NOT NECESSARY	49.20	-
	LESS 25% DISCOUNT		-1,005.93	-414.90
			3,017.77	1,244.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	40.00
1	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
			130.00	40.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		600.00	300.00
	LABOUR FOR SPRAYPAINTING.		600.00	250.00
	WIRING CHECK .		80.00	30.00
	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS .	NOT NECESSARY	150.00	-
			1,430.00	580.00
	GRAND TOTAL		4,577.77	1,864.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CS/SMO22009159/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.