

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009166/KNCQ2**Date:** 17/10/2022**REFERENCE**

Insured/Claimant: MUHAMAD MURAD BIN KASMANI Policy No: SP2000575096-01
Date of Loss: 16/09/2022 Nature of Claim: OD Claim No: 202222006819JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU121R**
Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE170408
Reg. Date: 28/10/2010 (Man. Year: 2010) Chassis No: MR053BK4107057387
Colour: Metallic Pearl White Odometer: 151071 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$33,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,996.80	2,874.80	1,122.00	28.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,420.00	930.00	39.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,346.80	4,294.80	2,052.00	32.33
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,346.80	3,694.80	2,652.00	41.78
+ GST 7.00/7.00% (S\$)	444.28	258.64	185.64	41.78
Nett Amount (S\$)	6,791.08	3,953.44	2,837.64	41.78

INSPECTION

Date of Assignment: 19/09/2022 Present Location: Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected: 19/09/2022 Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2022)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU121R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	450.00 F	*450.00 F
2	1		*Bonnet Lock (WCP)	Repair	70.00 F	*- F
3	1		*Brace Panel (WCP)	Bent	50.00 F	*50.00 F
4	1		*LH HeadLamp (WCP)	Mtg Cracked	360.00 F	*360.00 F
5	1		*RH HeadLamp (WCP)	Mtg Cracked	360.00 F	*360.00 F
6	1		*Front Grille (WCP)	Cracked	180.00 F	*180.00 F
7	1		*Front Grille Logo (WCP)	Necessary	28.00 F	*28.00 F
8	1		*Radiator (WCP)	Serviceable	550.00 F	*- F
9	1		*Radiator Support Panel (WCP)	Repair	330.00 F	*- F
10	1		*Front Bumper (WCP)	Cracked	265.00 F	*265.00 F
11	1		*Front Bumper Reinforcement (WCP)	Bent	170.00 F	*170.00 F
12	1		*Front Bumper Sponge (WCP)	Cracked	75.00 F	*75.00 F
13	1		*LH Front Bumper Side Retainer (WCP)	Distorted	40.00 F	*40.00 F
14	1		*RH Front Bumper Side Retainer (WCP)	Distorted	40.00 F	*40.00 F
15	1		*Front Bumper Lower Grille (WCP)	Serviceable	70.00 F	*- F
16	1		*Air Con Condenser (WCP)	Punctured	380.00 F	*380.00 F
17	1		*Front Bumper Clip	Necessary	60.00 FS	*60.00 FS
18	1		*LH Air Guide (WCP)	Distorted	60.00 F	*60.00 F
19	1		*RH Air Guide (WCP)	Distorted	60.00 F	*60.00 F
<u>Supplementary #1</u>						
20	1		*FRONT NUMBER PLATE (WCP)	Missing	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,643.00	2,623.00
+ Margin on L,N Items 10.00/10.00% (S\$)	353.80	251.80
Total Parts (S\$)	3,996.80	2,874.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check wiring and focus headlamp	New	50.00	20.00
2	To vacuum, re-oil and re-gas air con	New	120.00	100.00
3	To cut out/re-weld radiator support panel, repair front chassis, front fenders including replacement of parts	New	880.00	500.00
4	To spray paint on bonnet, front bumper, radiator support panel, LH/RH front fender	New	1,300.00	800.00
Gross Labour Cost (S\$)			2,350.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >