

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009167/AQCE2**Date:** 01/12/2022**REFERENCE**

Insured/Claimant:	CHUA BAN LEE (CAI WANLI)	Policy No:	1900088959-01	
Date of Loss:	12/09/2022	Nature of Claim:	OD	Claim No: 3296778961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3337S		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK077150
Reg. Date:	23/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF48KA042003
Colour:	Bronze	Odometer:	35163 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,129.00	1,022.40	5,106.60	83.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,032.00	2,432.00	3,600.00	59.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,161.00	3,454.40	8,706.60	71.59
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	11,361.00	2,654.40	8,706.60	76.64
+ GST 7.00/7.00% (S\$)	795.27	185.81	609.46	76.64
Nett Amount (S\$)	12,156.27	2,840.21	9,316.06	76.64

INSPECTION

Date of Assignment:	19/09/2022	
Date Inspected:	16/09/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	3,188.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	487.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
5	1		*REAR BUMPER BRACKET - RH	Not Necessary	130.00 FS	*- FS
6	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	46.00 FS	*- FS
7	1		*REAR BUMPER LOWER GUIDE SECTION - RH	Not Necessary	26.00 FS	*- FS
8	1		*REAR BUMPER HOLDING STRAP - RH	Not Necessary	94.00 FS	*- FS
9	1		*REAR BUMPER UPPER GUIDE SECTION - RH	Not Necessary	51.00 FS	*- FS
10	1		*REAR ALUMINIUM RIM	Cut	1,278.00 FS	*1,022.40 FS
11	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,129.00 1,022.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR	New	2,800.00	1,100.00
4	TO RENEW RHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,032.00	2,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >